

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

YEE HONG PAK
BLK 308C ANCHORVALE ROAD #08-22
SINGAPORE 543308

Contact : 96406310

TAX INVOICE

Repair Code : CLM17516

Date in : 12/12/2022

Vehicle Num. : SNC3400C

Model : HONDA SHUTTLE 1.5G CVT SENSING

Chassis/Eng# : GK82102905/L15B6023398

TP chuan
Veron

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Rehd</i>	1	1150.40	1,150.40 <i>885</i>
REAR BUMPER CENTER CHROME MOULDING <i>Crushed</i>	1	148.20	148.20
REAR BUMPER INNER SPONGE L/R <i>Crushed</i>	2	98.50	197.00
REAR BUMPER REFLECTOR L/R <i>new</i>	2	49.20	98.40
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	28.40	56.80
REAR BUMPER TOW HOOK COVER <i>new</i>	1	29.50	29.50
REAR END PANEL <i>Distorted</i>	1	560.20	560.20
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	50.20	50.20
REAR END PANEL INNER TOP GARNISH <i>Rehd</i>	1	155.40	155.40
REAR TAILGATE <i>Distorted</i>	1	1293.40	1,293.40
REAR TAILGATE 'LOGO' EMBLEM <i>3 new</i>	1	39.40	39.40
REAR TAILGATE 'SHUTTLE' EMBLEM	1	59.80	59.80
REAR TAILGATE HINGES L/R <i>new</i>	2	59.40	118.80
REAR TAILGATE INNER PULL HANDLE <i>Rehd</i>	1	29.40	29.40
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	9.40	18.80
REAR TAILGATE INNER TRIM BOARD <i>Crushed</i>	1	280.40	280.40
REAR TAILGATE LOCK STRIKER <i>new</i>	1	49.20	49.20
REAR TAILGATE MECHANISM LOCK <i>Rehd</i>	1	228.40	228.40

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

YEE HONG PAK
BLK 308C ANCHORVALE ROAD #08-22
SINGAPORE 543308

Contact : 96406310

TAX INVOICE

Repair Code : CLM17516
Date in : 12/12/2022
Vehicle Num. : SNC3400C
Model : HONDA SHUTTLE 1.5G CVT SENSING
Chassis/Eng# : GK82102905/L15B6023398

REAR TAILGATE NUMBER PLATE LAMP L/R	2	159.80	319.60
REAR TAILGATE OUTER GARNISH WITH CHROME	1	410.90	410.90
REAR TAILGATE REFELCTOR L/R	2	420.90	841.80
REAR TAILGATE WEATHER STRIP	1	168.20	168.20
REAR TAILGATE WINDSCREEN MOULDING	1	149.30	149.30
REAR TAILLAMP L/R	2	520.90	1041.80
Subtotal before discount			7,495.30
Percentage discount 20%			1,499.06
Sub-total 1			5,996.24
REAR BUMPER CLIPS - SET	1	50.00	50.00
REAR BUMPER REVERSE SENSOR - SET	1	280.00	280.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	40.00	40.00
REAR TAILGATE CAMERA	1	800.00	800.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	50.00	50.00
REAR TAILGATE NUMBER PLATE	1	25.00	25.00
REAR TAILGATE NUMBER PLATE HOLDER	1	50.00	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	1	40.00	40.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

YEE HONG PAK
BLK 308C ANCHORVALE ROAD #08-22
SINGAPORE 543308

Contact : 96406310

TAX INVOICE

Repair Code : CLM17516

Date in : 12/12/2022

Vehicle Num. : SNC3400C

Model : HONDA SHUTTLE 1.5G CVT SENSING

Chassis/Eng# : GK82102905/L15B6023398

REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2	25.00	<i>10</i> 50.00
Subtotal before discount <i>360</i>			1,465.00
Percentage discount 0%			0.00
Sub-total 2			1,465.00
Parts-total			7,461.24

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total

Parts & Labour Total

✓ 80.00

120 150.00

60 100.00

800 1,000.00

800 1,000.00

60 120.00

✓ 80.00

2,530.00

9,991.24

*** This is a computer-generated document which requires no signature. ***

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

page 3

Adrian
4/5 12/12/22

06 Aug

total: 7214.16

4/5: 57K ✓