

ble OK

HEEEV

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SJS7342Z

Make & Model: Volkswagen Scirocco

Chassis number: WVWZZZ13AV410762

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Tailgate	1	\$bt 1,601.83
2	Tailgate centre emblem	1	\$net 68.50
3	Tailgate lock	1	\$jm 167.50
4	Tailgate lock catch	1	\$x nn 74.30
5	Tailgate weatherstrip	1	\$fwi 214.60
6	Tailgate inner trim board	1	\$Bri 286.50
7	Tailgate wiper motor	1	\$x nn 532.10
8	Rear bumper	1	\$de 1,103.40
9	Rear bumper RH reflector	1	\$x nn 78.90
10	Rear bumper LH reflector	1	\$x nn 78.90
11	Rear bumper number plate RH lamp	1	\$cna 55.70
12	Rear bumper number plate LH lamp	1	\$cna 55.70
13	Rear bumper inner centre bracket	1	\$one 73.20
14	Rear bumper RH side retainer	1	\$mly 41.20
15	Rear bumper LH side retainer	1	\$x nn 41.20
16	Rear bumper reinforcement	1	\$bb 453.17
17	LH taillamp	1	\$aut 464.30
18	LH taillamp panel	1	\$x nn 178.20
19	LH taillamp lock clips	1set	\$x nn 28.00
20	RH taillamp	1	\$aut 464.30
21	RH taillamp panel	1	\$x nn 178.20
22	RH taillamp lock clips	1set	\$x nn 28.00
23	End panel	1	\$bb 785.90
24	End panel garnish	1	\$de 119.80
25	Rear fender RH inner trim	1	\$x nn 343.20
26	Rear fender LH inner trim	1	\$x nn 343.20
27	Rear spare tyre panel top board	1	\$x nn 287.50

528

28	Rear spare tyre panel	1	\$ AK 874.20
29	Exhaust silencer	1	\$ 761 1,548.90
30	Exhaust silencer gasket	1	\$ 361 67.00

1,459

\$ 10,637.40

Parts less 10% \$ 1,063.74

Total \$ 9,573.66

No.	Special Nett Items	Qty	Amount S\$
1	Tailgate inner trim board clips	1set	\$ 300 80.00
2	Tailgate windscreen glass sealant	1	\$ 400 80.00
3	Tailgate windscreen glass inner seal	1	\$ 300 60.00
4	Rear bumper clips	1set	\$ 200 80.00
5	Rear bumper reverse sensor	1set	\$ 200 350.00
6	Rear bumper reverse camera	1	\$ X 750.00
7	End panel garnish clips	1set	\$ 200 60.00
8	Rear fender LH inner trim clips	1set	\$ X 60.00
9	Rear fender RH inner trim clips	1set	\$ X 60.00
10	Rear number plate	1	\$ 200 30.00
11	End panel joint sealant	1	\$ 400 80.00
12	End panel inner garnish	1	\$ X 60.00
13	RH taillamp panel joint sealant	1	\$ X 50.00
14	LH taillamp panel joint sealant	1	\$ X 50.00

45

Total: \$ 1,890.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	700 \$ 1,500.00
2	Spray painting on affected areas and panels	700 \$ 1,200.00
3	Check wiring and lighting system on affected areas	50 \$ 100.00
4	Apply rust coating chemical on affected areas and panels	30 \$ 120.00
5	Remove and reinstall tailgate windscreen glass and sealants to assist repair	120 200.00

6	Remove and replace tailgate inner mechanism to new tailgate	\$ 60	180.00
7	Remove and replace rear bumper reverse sensors to assist repair	\$ 30	100.00
8	Remove and replace rear inner trims, garnish and boards to assist repair	\$ 60	450.00
9	Remove and replace exhaust silencer and gasket to assist repair	\$ 80	240.00

Total: \$ 4,090.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 9,573.66

Special Nett \$ 1,890.00

Labour: \$ 4,090.00

Total Amount: \$ 15,553.66

Tanpin 9779 5749

WP' 14/12/22 @ 1630

c/s Repair after repair

Tanpin @ khanto.com

6 days

- To check consistency of accident
- To check part prices