

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : TP/122022/5841
Date : 12-12-2022
Accident Date : 09-12-2022

Vehicle Details

Make & Model : Volvo S60 D2
Chassis No : YV1FS84ABE2270254
Registration No : SJW1222E

Third Party Vehicle Details

Registration No : SNG6660C

S/N	Description	Qty	Amount (\$)
1	BOOTLID / <i>Bac</i>	1.00	2215 ✓ \$2,905.00
2	BOOTLID EMBLEM /	1.00	\$128.00 ✓
3	BOOTLID "D2" EMBLEM / <i>me</i>	1.00	68 ✓ \$98.40
4	BOOTLID "S60" EMBLEM /	1.00	85 ✓ \$115.00
5	BOOTLID RH REFLECTOR = <i>cut</i>	1.00	\$256.30 ✓
6	BOOTLID LH REFLECTOR	1.00	\$256.30 ✓
7	BOOTLID INNER LOCK / <i>BT</i>	1.00	245 ✓ \$587.60
8	BOOTLID RUBBER / <i>tin</i>	1.00	\$192.70 ✓
9	RH TAILLAMP / <i>cut</i>	1.00	\$511.70 ✓
10	LH TAILLAMP	1.00	\$511.70 ✓
11	RH TAILLAMP LOWER BRACKET ? <i>nn</i>	1.00	\$108.70 X
12	LH TAILLAMP LOWER BRACKET ? <i>nn</i>	1.00	\$108.70 X
13	REAR BUMPER / <i>ee</i>	1.00	1845 ✓ \$2,087.70
14	REAR BUMPER PARKING SENSOR / <i>pm</i> 245 pc	4.00	980 ✓ \$1,180.00
15	REAR BUMPER TOWING COVER X <i>nn</i>	1.00	\$92.00 X
16	REAR BUMPER CENTER PAD - BLACK / <i>cut</i>	1.00	685 ✓ \$780.10
17	REAR BUMPER RH SIDE RETAINER X <i>nn</i>	1.00	\$96.00 X
18	REAR BUMPER LH SIDE RETAINER / <i>ee</i>	1.00	\$96.00 ✓
19	REAR BUMPER REINFORCEMENT ?	1.00	765 ✓ \$1,621.60
20	REAR BUMPER CLIPS / <i>del.</i>	10.00	30 ✓ \$120.00
21	REAR KEYLESS ANTENNA SENSOR ? <i>BR</i>	1.00	\$219.70 ✓
22	REAR END PANEL / <i>Bac</i> <i>phase</i>	1.00	\$648.50 ✓
23	REAR END PANEL TOP TRIM / <i>ee</i>	1.00	300 ✓ \$435.00
24	REAR EXHAUST SILENCER ? <i>BT</i>	1.00	1085 ✓ \$1,148.60
25	REAR EXHAUST SILENCER HEAT SHIELD ? <i>BT</i>	1.00	165 ✓ \$522.70
26	REAR SPARE TYRE PANEL TOP COVER ? <i>BR</i>	1.00	586 ✓ \$697.30

11,874.90
-10%
10,687.41

Discount: -10%

\$15,525.30
(\$1,552.53)

\$13,972.77

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

27	REAR NO.PLATE - <i>cut</i>	1.00	\$40.00 ✓
28	TO REPAIR DAMAGES	1.00	\$980.00 <i>700</i>
29	TO SPRAY PAINTING	1540 1.00	\$1,100.00 <i>800</i>

Subtotal w/o GST:

\$16,092.77

*6 Days.
part by part.
before paint parts.
Gus Og
13/12/22*

12,227.41

L/S - 9781.92
= 9800

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Iswan

This is a computer-generated document. No signature is required.