

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLA8471Z/2212173

05th January 2023

The Manager
Motor Claim Department
Lonpac Insurance Bhd
300, Beach Road
#17-04/07 The Concourse
Singapore 199555

Date of Accident : 12th December 2022

Location : Redhill close towards Jalan Bukit Merah

Name of Policyholder : Tan See See

Policy No : Z22PC05030979

Vehicle No : SLA 8471 Z Honda Vezel

Estimated Supply of Parts & Labours

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Front bumper fascia	1	170.00	\$ 170.00
2	Front bumper side retainer RH	1	10.00	\$ 10.00
3	Front bumper reinforcement beam	1	180.00	\$ 180.00
4	Front bumper fog lamp cover RH	1	15.00	\$ 15.00
5	Front bumper fog lamp RH	1	50.00	\$ 50.00
6	Front bumper towing cover	1	12.00	\$ 12.00
7	Front bumper lower lip	1	120.00	\$ 120.00
8	Front fender RH	1	180.00	\$ 180.00
9	Front fender cowling RH	1	35.00	\$ 35.00
10	Front fender wheel arch garnish	1	40.00	\$ 40.00
11	Headlamp RH	1	780.00	\$ 780.00
12	Headlamp bracket RH	1	20.00	\$ 20.00
13	Wheel house extension panel RH	1	100.00	\$ 100.00
14	Windscreen washer tank	1	45.00	\$ 45.00
15	Bonnet	1	380.00	\$ 380.00
16	Front side frame gusset RH	1	40.00	\$ 40.00
17	Plate R side frame	1	35.00	\$ 35.00
18	Headlamp LH	1	780.00	\$ 780.00
19	Headlamp bracket LH	1	20.00	\$ 20.00
20	Front grille	1	180.00	\$ 180.00
				\$ 3,192.00

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLA8471Z/2212173

05th January 2023

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
	Balance b/f			\$ 3,192.00
21	Front fender arch garnish LH	1	40.00	\$ 40.00
				\$ 3,232.00
	Cost Plus		15%	\$ 484.80
				\$ 3,716.80
22	Front bumper clips	1set	20.00	\$ 20.00
23	Front fender cowling clips	1set	20.00	\$ 20.00
24	Front fender wheel arch garnish clips	1set	20.00	\$ 20.00
				\$ 3,776.80
<u>Labour Charges :-</u>				<u>Amounts</u>
Cut out, renew, knocking & welding front fender RH, front wheel house extension panel RH, front headlamp panel RH, remove & install all damage parts, straighten front chassis & re-align body				\$ 900.00
Computerise wheel alignment				\$ 80.00
Spray painting on damage parts				\$ 1,000.00
Check all lighting after repairs				\$ 30.00
				\$ 5,786.80
Add 7% GST				\$ 405.08
Total Amount				\$ 6,191.88

S/ Dollars :- Six Thousand One Hundred Ninety One And Cents Eighty Eight Only.