

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLA8471Z/2212173

13th December 2022

The Manager
Motor Claim Department
Lonpac Insurance Bhd
300, Beach Road
#17-04/07 The Concourse
Singapore 199555

Date of Accident : 12th December 2022

Location : Redhill close towards Jalan Bukit Merah

Name of Policyholder : Tan See See

Policy No : Z22PC05030979

Vehicle No : SLA 8471 Z Honda Vezel

Estimated Supply of Parts & Labours

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Front bumper fascia	1	170.00	\$ 170.00
2	Front bumper side retainer RH	1	10.00	\$ 10.00
3	Front bumper reinforcement beam	1	180.00	\$ 180.00
4	Front bumper fog lamp cover RH	1	15.00	\$ 15.00
5	Front bumper fog lamp RH	1	115.00	\$ 115.00
6	Front bumper towing cover	1	12.00	\$ 12.00
7	Front bumper clips	1set	20.00	\$ 20.00
8	Front bumper lower lip	1	120.00	\$ 120.00
9	Front bumper dust cover	1	70.00	\$ 70.00
10	Front bumper lower grille	1	55.00	\$ 55.00
11	Front fender RH	1	180.00	\$ 180.00
12	Front fender cowling RH	1	70.00	\$ 70.00
13	Front fender cowling clips	1set	20.00	\$ 20.00
14	Front fender wheel arch garnish	1	40.00	\$ 40.00
15	Front fender wheel arch garnish clips	1set	20.00	\$ 20.00
16	Headlamp RH	1	780.00	\$ 780.00
17	Headlamp bracket RH	1	20.00	\$ 20.00
18	Headlamp panel RH	1	120.00	\$ 120.00
19	Wheel house extension panel RH	1	100.00	\$ 100.00
20	Windscreen washer tank	1	45.00	\$ 45.00
				\$ 2,162.00

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLA8471Z/2212173

13th December 2022

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
	Balance b/f			\$ 2,162.00
21	Windscreen washer tank motor	1	35.00	\$ 35.00
22	Horn	1	45.00	\$ 45.00
				\$ 2,242.00
		Cost Plus	15%	\$ 336.30
				\$ 2,578.30

Labour Charges :-

	<u>Amounts</u>
Cut out, renew, knocking & welding front fender RH, front wheel house extension panel RH, front headlamp panel RH, remove & install all damage parts, straighten front chassis & re-align body	\$ 1,080.00
Computerise wheel alignment	\$ 120.00
Spray painting on damage parts	\$ 1,200.00
Check all lighting after repairs	\$ 35.00
Labour Charge	\$ 2,435.00
Total Amount	
	\$ 5,013.30

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.