

Name & Address:

Vehicle No:

Date:

SNB6046C

19-Mar-23

Brand & Model:

Franchise:

MG HS

MG

Email/Fax No:

Contact No:

Chassis/VIN No:

Contact Person (Eurokars):

LSJA24U97MN081892

JESS

Type of Claim:

Policy No:

Date Of Registration:

Contact No (Eurokars):

OWN DAMAGE

31/08/2021

6331 0680

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	UNIT PRICE	QTY	MARK	REVISED	PRICE
1	REAR FENDER RH	M30131603CC-SEPP	780.00	1		780.00	780.00
2	QUARTER GLASS RH	M10400535	260.00	1		260.00	260.00
3	REAR DOOR RH	M10005112-SPCP	1,500.00	1		1,500.00	1,500.00
4	FILM STICKER NO.1 REAR DOOR RH	M10635718	67.00	1		67.00	67.00
5	UPPER FILM STICKER REAR DOOR RH	M10367172	52.00	1		52.00	52.00
6	FILM STICKER NO.2 REAR DOOR RH	M10635720	67.00	1		67.00	67.00
7	APPLIQUE REAR DOOR RH	M10367184	4.00	1		-	4.00
8	WEATHERSTRIP DOOR REAR RH	M10367144	99.00	1		99.00	99.00
9	HANDLE REAR DOOR RH	M10285736-SPRP	58.00	1		58.00	58.00
10	CAP HANDLE REAR DOOR RH	M10285745-SPRP	26.00	1		26.00	26.00
11	GASKET HANDLE REAR DOOR RH	M10285740	2.50	1		2.50	2.50
12	BASE HANDLE REAR DOOR RH	M10508202	28.00	1		28.00	28.00
13	WHEEL ARCH REAR DOOR RH	M10395320	58.00	1		58.00	58.00
14	WHEEL ARCH REAR FENDER RH	M10646894	67.00	1		67.00	67.00
15	GARNISH LOWER DOOR REAR RH	M10423727	150.00	1		150.00	150.00
16	GARNISH LOWER FRONT DOOR RH	M10423725	241.00	1		241.00	241.00
17	CLIP	M10068498	2.00	10		20.00	20.00
18	LOWER MOULDING FRONT DOOR RH (SILVER)	M10367162	99.00	1		99.00	99.00
19	HANDLE FRONT DOOR RH	M10683364-SPRP	150.00	1		150.00	150.00
20	CAP HANDLE FRONT DOOR RH	M10567065-SPRP	26.00	1		-	26.00
21	GASKET FRONT DOOR RH	M10285740	2.50	1		-	2.50
22	SIDE MIRROR RH	M10577198-SPRP	380.00	1		380.00	380.00
23	*** SUPPLEMENTARY ITEMS ***		-			-	-
24	PLUG-FRT S/D/ O/S HDL ACC HOLE	M10095456	2.50	1		2.50	NEC ✓ -
25	NUT-RR BPR FASCIA	M50012569	2.00	5		10.00	NEC ✓ -

Sub-Total (Parts Price) 4,117.00 4,137.00

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	REPLACE RHR DOOR, RHR FENDER. REPAIR RHF DOOR, REAR BUMPER.	2,640.00	1,320.00
2	SPRAY RHF DOOR, RHR DOOR, RHR FENDER, REAR BUMPER.	1,890.00	2,100.00

3	TO REMOVE & REFIT QUARTER GLASS RH AND CONDUCT WATER TEST LEAK.	280.00	280.00
4	TO SUPPLY SEALANT ON THE QUARTER GLASS RH.	80.00	80.00
5	TO SUPPLY SOLAR FILM QUARTER GLASS RH.	140.00	140.00
6	TO TRANSFER REAR RH DOOR MECHANISMS.	-	330.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150.00	200.00
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180.00	250.00
9	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOUC).	80.00	150.00
10	SUNDRIES	-	20.00

Survey Date & Time:	Repair Days:	Excess:
---------------------	--------------	---------

Surveyor Remarks:

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price)	5,440.00	4,870.00
	REVISED	PRICE
Parts Price	4,117.00	4,137.00
Labour Price	5,440.00	4,870.00
Total (Initial Estimate)	9,557.00	9,007.00
Supp 1	-	-
Supp 2	-	-
Supp 3	-	-
Total (Before Excess)	9,557.00	9,007.00
Less Excess	500.00	-
TOTAL (After Excess)	9,057.00	9,007.00
GST 7%	633.99	630.49
GRAND TOTAL	9,690.99	9,637.49