

Name & Address:
 ERGO INSURANCE PTE. LTD.
 5 Temasek Boulevard
 #04-01 Suntec Tower Five
 Singapore 038985

Vehicle No:
 SNB6046C
 Brand & Model:
 MG HS
 Chassis/VIN No:
 LSJA24U97MN081892
 Date Of Registration:
 31/08/2021

Date:
 12-Dec-22
 Franchise:
 MG
 Contact Person (Eurokars):
 JESS
 Contact No (Eurokars):
 6331 0680

Email/Fax No:
 Type of Claim:
 OWN DAMAGE

Contact No:
 Policy No:

PARTS / MATERIAL CHARGES MARK = Survey Marking (Key "A" if item is approved)

NO	DESCRIPTION	PART NO.	UNIT PRICE	QTY	MARK	REVISED	PRICE
1	REAR FENDER RH	30131603CC-SEPP	780.00	1		-	bf 780.00
2	QUARTER GLASS RH	10400535	260.00	1		-	re 260.00
3	REAR DOOR RH	10005112-SPCP	1,500.00	1		-	bf 1,500.00
4	FILM STICKER NO.1 REAR DOOR RH	10635718	67.00	1		-	re 67.00
5	UPPER FILM STICKER REAR DOOR RH	10367172	52.00	1		-	re 52.00
6	FILM STICKER NO.2 REAR DOOR RH	10635720	67.00	1		-	re 67.00
7	APPLIQUE REAR DOOR RH	10367184	4.00	1		-	? 4.00
8	WEATHERSTRIP DOOR REAR RH	10367144	99.00	1		-	re 99.00
9	HANDLE REAR DOOR RH	10285736-SPRP	58.00	1		-	his 58.00
10	CAP HANDLE REAR DOOR RH	10285745-SPRP	26.00	1		-	re 26.00
11	GASKET HANDLE REAR DOOR RH	10285740	2.50	1		-	re 2.50
12	BASE HANDLE REAR DOOR RH	10508202	28.00	1		-	? dis 28.00
13	WHEEL ARCH REAR DOOR RH	10395320	58.00	1		-	cut 58.00
14	WHEEL ARCH REAR FENDER RH	10646894	67.00	1		-	cut 67.00
15	GARNISH LOWER DOOR REAR RH	10423727	150.00	1		-	cut 150.00
16	GARNISH LOWER FRONT DOOR RH	10423725	241.00	1		-	cut 241.00
17	CLIP	####	2.00	10		-	re 20.00
18	LOWER MOULDING FRONT DOOR RH (SILVER)	10367162	99.00	1		-	re 99.00
19	HANDLE FRONT DOOR RH	10683364-SPRP	150.00	1		-	cut 150.00
20	CAP HANDLE FRONT DOOR RH	10567065-SPRP	26.00	1		-	x 26.00
21	GASKET FRONT DOOR RH	####	2.50	1		-	x 2.50
22	SIDE MIRROR RH	10577198-SPRP	380.00	1		-	cut 380.00
23							

Sub-Total (Parts Price) 4,137.00

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REPLACE REAR FENDER RH AND REAR DOOR RH. 660	2640	1,320.00
2	TO RESPRAY REAR FENDER RH, REAR & FRONT DOOR RH, FRONT & REAR DOOR HANDLE RH AND COVER SIDE MIRROR. 630	1890	2,100.00
3	TO REMOVE & REFIT QUARTER GLASS RH AND CONDUCT WATER TEST LEAK.	✓	280.00

Name & Address:
ERGO INSURANCE PTE. LTD.
 5 Temasek Boulevard
 #04-01 Suntec Tower Five
 Singapore 038985

Vehicle No:
SN66046C
 Brand & Model:
MG HS
 Chassis/VIN No:
LSJA24U97MNO81892
 Date Of Registration:
31/08/2021

Date:
2-Feb-23
 Franchise:
MG
 Contact Person (Eurokars):
JESS
 Contact No (Eurokars):
6331 0680

Email/Fax No: _____ Contact No: _____
 Type of Claim: _____ Policy No: _____
OWN DAMAGE

PARTS / MATERIAL CHARGES						MARK = Survey Marking [Key "A" if item is approved]	
NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE	
1	COVER HOLE HANDLE RH	10095456	1			\$ <i>dis</i> / 2.50	
2	GROMMET SCREW	50012569	5			\$ <i>net</i> / 10.00	
3						\$ -	

Sub-Total (Parts Price) \$ - \$ 12.50

LABOUR / SERVICES CHARGES			
NO	DESCRIPTION	REVISED	PRICE
1	TO REPAIR WHEEL HOUSE REAR RH.		\$ ✓ 660.00
2	TO RESPRAY WHEEL HOUSE REAR RH.		\$ ✓ 630.00

Survey Date & Time:	Repair Days:
---------------------	--------------

Sub-Total (Labour Price) \$ - \$ 1,290.00

Surveyor Remarks:

Parts Price \$ - \$ 12.50
 Labour Price \$ - \$ 1,290.00
 Total (Supp 1) \$ - \$ 1,302.50

Add 2 days
Total: 7 + 2 = 9 days.