

Name & Address:  
**ERGO INSURANCE PTE. LTD.**  
 5 Temasek Boulevard  
 #04-01 Suntec Tower Five  
 Singapore 038985

Vehicle No:  
 SNB6046C  
 Brand & Model:  
 MG HS  
 Chassis/VIN No:  
 LSJA24U97MN081892  
 Date Of Registration:  
 31/08/2021

Date:  
 12-Dec-22  
 Franchise:  
 MG  
 Contact Person (Eurokars):  
 JESS  
 Contact No (Eurokars):  
 6331 0680

Email/Fax No:  
 Contact No:  
 Type of Claim:  
 OWN DAMAGE  
 Policy No:

PARTS / MATERIAL CHARGES		MARK = Survey Marking [Key "A" if item is approved]					
NO	DESCRIPTION	PART NO.	UNIT PRICE	QTY	MARK	REVISED	PRICE
1	REAR FENDER RH	30131603CC-SEPP	780.00	1		-	<del>bf</del> 780.00
2	QUARTER GLASS RH	10400535	260.00	1		-	<del>re</del> 260.00
3	REAR DOOR RH	10005112-SPCP	1,500.00	1		-	<del>bf</del> 1,500.00
4	FILM STICKER NO.1 REAR DOOR RH	10635718	67.00	1		-	<del>re</del> 67.00
5	UPPER FILM STICKER REAR DOOR RH	10367172	52.00	1		-	<del>re</del> 52.00
6	FILM STICKER NO.2 REAR DOOR RH	10635720	67.00	1		-	<del>re</del> 67.00
7	APPLIQUE REAR DOOR RH	10367184	4.00	1		-	<del>X nn</del> 4.00
8	WEATHERSTRIP DOOR REAR RH	10367144	99.00	1		-	<del>re</del> 99.00
9	HANDLE REAR DOOR RH	10285736-SPRP	58.00	1		-	<del>his</del> 58.00
10	CAP HANDLE REAR DOOR RH	10285745-SPRP	26.00	1		-	<del>mis</del> 26.00
11	GASKET HANDLE REAR DOOR RH	10285740	2.50	1		-	<del>re</del> 2.50
12	BASE HANDLE REAR DOOR RH	10508202	28.00	1		-	<del>his</del> 28.00
13	WHEEL ARCH REAR DOOR RH	10395320	58.00	1		-	<del>cut</del> 58.00
14	WHEEL ARCH REAR FENDER RH	10646894	67.00	1		-	<del>cut</del> 67.00
15	GARNISH LOWER DOOR REAR RH	10423727	150.00	1		-	<del>cut</del> 150.00
16	GARNISH LOWER FRONT DOOR RH	10423725	241.00	1		-	<del>cut</del> 241.00
17	CLIP	####	2.00	10		-	<del>re</del> 20.00
18	LOWER MOULDING FRONT DOOR RH ( SILVER )	10367162	99.00	1		-	<del>re</del> 99.00
19	HANDLE FRONT DOOR RH	10683364-SPRP	150.00	1		-	<del>cut</del> 150.00
20	CAP HANDLE FRONT DOOR RH	10567065-SPRP	26.00	1		-	<del>X nn</del> 26.00
21	GASKET FRONT DOOR RH	####	2.50	1		-	<del>X nn.</del> 2.50
22	SIDE MIRROR RH	10577198-SPRP	380.00	1		-	<del>cut</del> 380.00
23			-				-

Sub-Total (Parts Price) - 4,137.00

LABOUR / SERVICES CHARGES		REVISED	PRICE
1	TO REPLACE REAR FENDER RH AND REAR DOOR RH. <i>660</i>	<i>2640 /</i>	1,320.00
2	TO RESPRAY REAR FENDER RH, REAR & FRONT DOOR RH, FRONT & REAR DOOR HANDLE RH AND COVER SIDE MIRROR. <i>630</i>	<i>1890 /</i>	2,100.00
3	TO REMOVE & REFIT QUARTER GLASS RH AND CONDUCT WATER TEST LEAK.	<i>✓</i>	280.00

4	TO SUPPLY SEALANT ON THE QUARTER GLASS RH.	✓	80.00
5	TO SUPPLY SOLAR FILM QUARTER GLASS RH.	✗	140.00
6	TO TRANSFER REAR RH DOOR MECHANISMS.	X	330.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150.	200.00
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	250.00
9	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU).	80.	150.00
10	SUNDRIES	X	20.00

Survey Date & Time:	Repair Days:	Excess:
---------------------	--------------	---------

Sub-Total (Labour Price)	-	4,870.00
	<b>REVISED</b>	<b>PRICE</b>
Parts Price	-	4,137.00
Labour Price	-	4,870.00
Total (Initial Estimate)	-	9,007.00
Supp 1	-	-
Supp 2	-	-
Supp 3	-	-
Total (Before Excess)	-	9,007.00
Less Excess	-	-
TOTAL (After Excess)	-	9,007.00
GST 7%	-	630.49
<b>GRAND TOTAL</b>	-	<b>9,637.49</b>

Surveyor Remarks:

Taufiq 97495719 WP 15/12/22 @ LOAN  
 Repairing before parts  
 Taufiq elhikmah.com 07days  
 Rent Ex: fba

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: