

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Melody Teoh

Date: 04 Jan 2023

**Preliminary Advice**

Vehicle No	: SNB6046C	Accident Date	: 03/12/2022
Make	: M.G. HS	Policy No.	: DMPG22009729
Assignment Date	: 13/12/2022	Excess	: S\$500.00
Date of Inspection	: 15/12/2022	Est. Duration of Repair	: 7
Inspection At	: TRANS EUOKARS PTE LTD (UBI) 5 UBI CLOSE SINGAPORE 408605		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,327.00
Revised Amount	:S\$	9,516.50
Check Items (Estimated)	:S\$	32.00
Total	:S\$	9,548.50
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	67,560.00
Salvage Value	:S\$	
Margin for Repair	:S\$	57,440.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.