

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 15 Dec 2022

Preliminary Advice

Vehicle No	: GBC1994K	Accident Date	: 29/11/2022
Make	: NISSAN CABSTAR	Policy No.	: SP2001288382
Assignment Date	: 13/12/2022	Excess	: S\$2,000.00
Date of Inspection	: 14/12/2022	Est. Duration of Repair	: 21 DAYS
Inspection At	: SME MOTOR PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	50,621.70
Revised Amount	:S\$	24,531.20
Check Items (Estimated)	:S\$	23,650.50
Total	:S\$	48,181.70

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	38,000.00
COE / PARF Rebate	:S\$	14,296.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,704.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The repairer agreed to repair the vehicle not more than \$23,000.00 on Lump Sum basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.