

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	22/AL/OD623 (12)
Policy No:	SP2001288382	Date of Loss:	29/11/2022
Vehicle Reg. No.:	GBC1994K	Driveable?	
Driver Age/Info:	31 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TMF AUTOMOTIVE PTE LTD		
Driver:	RAMAKRISHNAN RAMAIAH		
Make/Model:	NISSAN CABSTAR, 3.0 (M)	Vehicle Reg. Date:	18/07/2011
Vehicle Colour:	SILVER		
Engine No:	ZD30286998K	Chassis No:	JN1SC2F24Z0850071
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	21		
Remarks:	VEHICLE IN.		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS

Parts		Amount
Miscellaneous Items		43,501.70
Labour		210.00
Paintwork Labour		6,910.00
Towing		0.00
		0.00
	Gross Total (S\$)	50,621.70
	+ GST 7.00% (S\$)	3,543.52
	Nett Amount (S\$)	54,165.22

This claim is handled by: **CHIA PEI YING**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 13 Dec 2022)
Parts: N/A NISSAN CABSTAR 3.0 (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: SME Motor Pte Ltd/GBC1994K/13/12/2022 13:58
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT WINDSCREEN <i>Shattered</i>	0.00	0.00	✓ *550.00 F
2	1		*FRT WINDSCREEN MOULDING <i>h</i>	0.00	0.00	✓ *240.00 F
3	2		*WIPPER ARM <i>Broken</i>	0.00	0.00	✓ *160.00 F
4	2		*WIPPER BLADE <i>cut</i>	0.00	0.00	✓ *60.00 F
5	1		*WIPPER LINK <i>Beat</i>	0.00	0.00	✓ *120.00 F
6	1		*WIPPER MOTOR <i>?</i>	0.00	0.00	? *360.00 F
7	1		*WIPPER PANEL <i>Distorted</i>	0.00	0.00	✓ *320.00 F
8	1		*FRT PANEL <i>Distorted</i>	0.00	0.00	✓ *550.00 F
9	1		*FRT PANEL CABSTAR EMBLEM <i>h</i>	0.00	0.00	✓ *35.00 F
10	1		*FRT GRILLE <i>smashed</i>	0.00	0.00	✓ *245.00 F
11	1		*FRT GRILLE CENTER LOGO <i>h</i>	0.00	0.00	✓ *55.00 F
12	8		*FRT GRILLE CLIP <i>ok</i>	0.00	0.00	✓ *32.00 F
13	1		*FRT BUMPER <i>Distorted</i>	0.00	0.00	✓ *480.00 F
14	2		*FRT BUMPER BRACKET <i>Beat</i>	0.00	0.00	✓ *76.00 F
15	2		*HEADLAMP <i>smashed</i>	0.00	0.00	✓ *530.00 F
16	2		*FRT CORNER PANEL <i>Distorted</i>	0.00	0.00	✓ *440.00 F
17	2		*SIDE MIRROR	0.00	0.00	✓ *250.00 F
18	2		*SIDE MIRROR BASE COVER <i>Missing</i>	0.00	0.00	✓ *160.00 F
19	1		*LH SIDE MIRROR BRACKET <i>Missing</i>	0.00	0.00	✓ *160.00 F
20	1		*LH ROUND MIRROR	0.00	0.00	✓ *65.00 F
21	2		*HEADLAMP LOWER TRIM <i>Missing</i>	0.00	0.00	✓ *120.00 F
22	1		*ROOF PANEL <i>Distorted</i>	0.00	0.00	✓ *1,400.00 F
23	2		*FRT PILLAR OUTER <i>Distorted</i>	0.00	0.00	✓ *1,700.00 F
24	2		*FRT PILLAR INNER	0.00	0.00	✓ *560.00 F
25	1		*FLOOR PANEL <i>Beat</i>	0.00	0.00	✓ *900.00 F
26	1		*FRT CABIN BRACKET <i>Beat</i>	0.00	0.00	✓ *420.00 F
27	2		*FRT CABIN BRACKET BUSH <i>Distorted</i>	0.00	0.00	✓ *100.00 F
28	2		*FRT CABIN BRACKET SHAFT	0.00	0.00	✓ *360.00 F
29	1		*STEERING COLUMN <i>?</i>	0.00	0.00	? *1,400.00 F
30	1		*STEERING COUPLING <i>?</i>	0.00	0.00	? *300.00 F
31	1		*STEERING BOX <i>?</i>	0.00	0.00	? *650.00 F
32	1		*AIRCON CONDENSER <i>?</i>	0.00	0.00	? *650.00 F
33	1		*AIRCON FAN ASSY <i>?</i>	0.00	0.00	? *460.00 F
34	2		*AIRCON CONDENSER BRACKET <i>?</i>	0.00	0.00	? *320.00 F
35	1		*AIRCON LIQUID PIPE	0.00	0.00	? *165.00 F
36	1		*AIRCON DISCHARGE PIPE <i>?</i>	0.00	0.00	? *220.00 F
37	1		*ROOF UNDERLINING <i>crumpled</i>	0.00	0.00	✓ *480.00 F
38	2		*FRT PILLAR INNER TRIM <i>Beat</i>	0.00	0.00	✓ *240.00 F
39	1		*RH SUN VISOR <i>?</i>	0.00	0.00	? *110.00 F
40	1		*DASHBOARD ASSY <i>Beat</i>	0.00	0.00	✓ *2,800.00 F
41	1		*BRAKE BOOSTER <i>?</i>	0.00	0.00	? *1,100.00 F

SME Motor Pte Ltd/GBC1994K/13/12/2022 13:58. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
42	1		*BRAKE MASTER PUMP	0.00	0.00	*260.00
43	1		*BRAKE FLUID TANK	0.00	0.00	*280.00
44	1		*METER ASSY	0.00	0.00	*1,380.00
45	1		*ACCELERATOR PEDAL	0.00	0.00	*130.00
46	1		*ACCELERATOR PEDAL BRACKET	0.00	0.00	*140.00
47	1		*BRAKE PEDAL	0.00	0.00	*295.00
48	1		*BRAKE PEDAL BRACKET	0.00	0.00	*135.00
49	2		*STEERING WHEEL LOWER COVER	0.00	0.00	*160.00
50	1		*GEAR LEVER CABLE	0.00	0.00	*290.00
51	2		*FRT DOOR <i>Distorted</i>	0.00	0.00	*1,600.00
52	2		*FRT DOOR HINGE (TOP) <i>Distorted</i>	0.00	0.00	*120.00
53	2		*FRT DOOR HINGE (LOWER) <i>Distorted</i>	0.00	0.00	*120.00
54	2		*FRT DOOR LOCK <i>Open</i>	0.00	0.00	*240.00
55	2		*FRT DOOR INNER RUBBER	0.00	0.00	*190.00
56	2		*FRT DOOR OUTER MOULDING <i>Del'd</i>	0.00	0.00	*210.00
57	2		*FRT DOOR SIGNAL LAMP <i>Auth</i>	0.00	0.00	*70.00
58	2		*FRT DOOR INNER TRIMBOARD <i>Del'd</i>	0.00	0.00	*900.00
59	16		*FRT DOOR INNER TRIMBOARD CLIP <i>m</i>	0.00	0.00	*64.00
60	1		*DASHBOARD CROSSMEMBER	0.00	0.00	*680.00
61	1		*DASHBOARD WIRE HARNESS	0.00	0.00	*3,900.00
			NO STOCK			
62	1		*ENGINE MOUNTING	0.00	0.00	*280.00
63	1		*RADIATOR <i>Distorted</i>	0.00	0.00	*495.00
64	1		*FRT RH DOOR GLASS <i>Shattered</i>	0.00	0.00	*430.00
65	1		*FRT RH DOOR GLASS CHANNEL <i>Del'd</i>	0.00	0.00	*150.00
66	2		*FRT DOOR POWER WINDOW MOTOR	0.00	0.00	*590.00
67	2		*FRT DOOR GLASS GEAR	0.00	0.00	*190.00
68	2		*FRT DOOR LOWER RUBBER	0.00	0.00	*150.00
69	2		*FRT STEP GARNISH <i>Distorted</i>	0.00	0.00	*290.00
70	2		*FRT WHEEL ARC GARNISH	0.00	0.00	*170.00
71	1		*WASHER TANK <i>Del'd</i>	0.00	0.00	*95.00
72	1		*CABIN REAR PANEL	0.00	0.00	*4,300.00
73	1		*AIRCON BLOWER	0.00	0.00	*600.00
74	1		*AIRCON COOLING COIL	0.00	0.00	*1,300.00

F=Franchise part.

Sub Total (\$\$)	39,547.00
+ Margin on L,N Items 10.00% (\$\$)	3,954.70
Total Parts (\$\$)	43,501.70

SME Motor Pte Ltd/GBC1994K/13/12/2022 13:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	BRAKE OIL <i>FM</i>	✓ 25.00
2	1	ERP BRACKET	✓ 25.00
3	2	FRT DOOR COMPANY STICKER <i>mu</i>	✓ 50.00
4	1	FRT WINDSCREEN GUM <i>mu</i>	✓ 60.00
5	1	NUMBER PLATE <i>Dented</i>	✓ 25.00
6	1	RADIATOR COOLANT <i>mu</i>	✓ 25.00
Sub Total (S\$)			210.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	WIRE CHECKING	New	✓ 30.00
2	REMOVE & REFIX FRT WINDSCREEN	New	✓ 120.00
3	REMOVE & REFIX ROOF UNDERLINING	New	180 250.00
4	REMOVE & REFIX DASHBOARD	New	200 250.00
5	REMOVE & REFIX BRAKE BOOSTER AND MASTER PUMP	New	7 180.00
6	REMOVE & REFIX 1 SET ENGINE MOUNTING	New	7 200.00
7	REMOVE & REFIX CUSHION AND SEATS	New	150 180.00
8	LABOUR CHARGE	New	2400 3,200.00
9	SPRAY PAINTING	New	2030 2,500.00
Gross Labour Cost (S\$)			6,910.00

SME Motor Pte Ltd/GBC1994K/13/12/2022 13:58. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Adrian Lij
4/s 14/12/22
Not Authorised.
Excess \$21k

21 days