

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9773 6360

Email: mak.auburnauto@gmail.com

Vehicle No: SKK6366S

Model: TOYOTA NOAH HYBRID

QTY	Description	Repairer's Estimate
Spare Parts - List Items		
1	Front bonnet <i>Repair x</i>	\$ 1,800.00 X
1	Front bumper <i>el</i>	\$ 1,600.00 1025 ✓
1	Front bumper bracket <i>? ✓ BR</i>	\$ 135 x2 350.00 270 ✓
1	Front right headlamp <i>lt</i>	\$ 2,000.00 ✓
1	Front right fender <i>Repair x</i>	\$ 1,200.00 X
1	Front bumper grill <i>el</i>	\$ 1,200.00 565 ✓
1	Radiator grill <i>? X nn</i>	\$ 1,000.00 X
1	Front reinforcement bar <i>? X nn</i>	\$ 800.00 X

3860
-20%
3088

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 9,950.00

c/f: \$ 9,950.00

Special Nett Items **AMT S\$**

\$ -

S/N. Labour Charges

1	Remove and refit and panel beating	\$	1,000.00	400
2	Remove, refit and replaced damage and check up rear electrical wiring	\$	150.00	30
3	Remove and refit inner garnishes trim to assist repair	\$	200.00	X
4	To apply undercoating on replaced panel	\$	120.00	X
5	To Respray Painting.	\$	1,000.00	800

1230

\$ 2,470.00

GRAND TOTAL

\$ 12,420.00

4318

L/S - 3454.40
= 3450

4 Days.
Gen Ricq
8288 0282
13/12/22