

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9773 6360

Email: mak.auburnauto@gmail.com

Vehicle No: SKK6366S

Model: TOYOTA NOAH HYBRID

QTY	Description	Repairer's Estimate	
Spare Parts - List Items			
1	Front bonnet <i>Repair x</i>	\$	1,800.00
1	Front bumper <i>ll</i>	\$	1,600.00
1	Front bumper bracket <i>?</i>	\$	350.00
1	Front right headlamp <i>lt</i>	\$	2,000.00
1	Front right fender <i>Repair x</i>	\$	1,200.00
1	Front bumper grill <i>lt</i>	\$	1,200.00
1	Radiator grill <i>?</i>	\$	1,000.00
1	Front reinforcement bar <i>?</i>	\$	800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 9,950.00

c/f: \$ 9,950.00

Special Nett Items **AMT S\$**

\$ -

S/N. Labour Charges

- | | | | |
|---|---|-------------|-----|
| 1 | Remove and refit and panel beating | \$ 1,000.00 | 400 |
| 2 | Remove, refit and replaced damage and check up rear electrical wiring | \$ 150.00 | 30 |
| 3 | Remove and refit inner garnishes trim to assist repair | \$ 200.00 | X |
| 4 | To apply undercoating on replaced panel | \$ 120.00 | X |
| 5 | To Respray Painting. | \$ 1,000.00 | 800 |

\$ 2,470.00

GRAND TOTAL

\$ 12,420.00

4 Days.
Gen Ricq
8288 0282
13/12/22