



Pte Ltd



TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

REPAIR PERFORMANCE INVOICE

Vehicle number SKE656SR
Make / Model LEXUS ES300
Chassis number JTHB21B10002011548
Accident date 12/12/22
Reference 2212-13

Qty	Particulars	Unit Price - SGD \$
PARTS REPLACEMENT - LIST ITEMS		
1	FRONT BUMPER	1238.60
1	FRONT BUMPER RETAINER LH	53.59
1	FRONT BUMPER PDC SENSOR LH	540.54
1	FRONT BUMPER OUTER CHROME LH	265.21
1	FRONT HEADLAMP LH	4406.38
1	FRONT HEADLAMP LOWER BRACKET LH	38.30
1	FRONT FENDER LH	1921.15
1	FRONT FENDER INNER SHIELD LH	570.02
1	FRONT KNUCKLE ARM LH	875.38
1	FRONT KNUCKLE ARM BEARING LH	726.88
1	FRONT LOWER ARM LH	905.52
1	FRONT SHOCK ABSORBER LH	885.72
1	FRONT RIM LH	3398.90
		15826.19
	10% Less	3165.24
	Subtotal	12660.95
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1 SET	FRONT BUMPER CLIP	30.00
1 SET	FRONT FENDER INNER SHIELD CLIP	30.00
	Subtotal	60.00
LABOUR AND MISCELLANEOUS CHARGES		
1	CHECK WIRING AND LIGHTING SYSTEM	100.00
2	COMPUTERIZE AND CHECK WHEEL ALIGNMENT	200.00
3	REMOVE & REPLACE FRONT UNDERCARRIAGE	200.00
4	RE-PROGRAMME AFTER REPAIR	500.00
5	PANEL BEATING ON AFFECTED AREAS	1000.00
6	SPRAY PAINT 4G ON AFFECTED AREAS	1000.00
7	APPLY ANTI-RUST ON AFFECTED AREAS	150.00
	Subtotal	3150.00
	Granttotal	15870.95

11 fm

15/12/22

140 pm
3 days L/S

Total Parts = \$5265.54

10% = 526.55

= 4738.99

FT = 5428.99

20% = 1085.79

= 4343.19

≈ 4350

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: