

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22012477/KYA3Q2**Date:** 12/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900105966
Claimant Vehicle No :	SHC5969L	Insured Vehicle No :	SML8455B
Date of Loss:	13/11/2022	Nature of Claim:	TP
		Claim No:	6762492358SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5969L		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C002848
Reg. Date:	03/08/2015 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC282213
Colour:	Metallic White/Red	Odometer:	748899 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Firenza 7 mm	Rear Left Side:	Firenza 7 mm
Front Right Side:	Firenza 7 mm	Rear Right Side:	Firenza 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,519.90	6,321.88	6,198.02	49.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,460.00	1,590.00	2,870.00	64.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,979.90	7,911.88	9,068.02	53.40
Approved Total (Overridden) (\$\$)		3,550.00		
Nett Amount (\$\$)	16,979.90	3,550.00	13,429.90	79.09
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	12/12/2022		
Date Inspected:	12/12/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL FRT LH	Bent	2,844.66 FL	*2,844.66 FL
2	1		*DOOR MOULDING FRT LH	Serviceable	100.50 FL	*- FL
3	1		*DOOR HANDLE OUTER FRT LH	Serviceable	169.50 FL	*- FL
4	1		*DOOR HANDLE MODULE FRT LH	Serviceable	133.40 FL	*- FL
5	1		*DOOR REGULATOR FRT LH	Serviceable	501.40 FL	*- FL
6	1		*DOOR REGULATOR MOTOR FRT LH	Serviceable	758.10 FL	*- FL
7	1		*DOOR HINGE LOWER FRT LH	Repair	300.55 FL	*- FL
8	1		*DOOR PANEL REAR LH	Bent	2,844.66 FL	*2,844.66 FL
9	1		*DOOR HANDLE OUTER REAR LH	Serviceable	42.10 FL	*- FL
10	1		*DOOR HANDLE MODULE REAR RH	Serviceable	133.40 FL	*- FL
11	1		*DOOR REGULATOR REAR LH	Serviceable	450.60 FL	*- FL
12	1		*DOOR REGULATOR MOTOR REAR LH	Serviceable	758.10 FL	*- FL
13	1		*DOOR HINGE UPPER REAR LH	Repair	241.60 FL	*- FL
14	1		*DOOR HINGE LOWER REAR LH	Repair	169.90 FL	*- FL
15	1		*ROCKER PANEL OUTER LH	Bent	1,184.99 FL	*1,184.99 FL
16	1		*FENDER PANEL REAR LH	Repair	1,933.20 FL	*- FL
17	1		*WHEELARCH REAR LH	Repair	275.40 FL	*- FL
18	2		*DOOR TRIM CLIP	Not Necessary	140.00 FS	*- FS
19	2		*DOOR MOULDING CLIP	Not Necessary	140.00 FS	*- FS
20	1		*DOOR STICKER TRANSCAB	Necessary	100.00 FS	*60.00 FS
21	1		*DOOR STICKER 65553333	Necessary	100.00 FS	*60.00 FS
22	1		*DOOR STICKER CLASSIC	Necessary	100.00 FS	*15.00 FS
23	1		*FENDER CLIP	Not Necessary	70.00 FS	*- FS
24	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
25	1		*DOOR HINGE UPPER FRT LH	Repair	274.50 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,831.56	7,009.31
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,311.66	687.43
Total Parts (\$\$)	12,519.90	6,321.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	230.00	90.00
2	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	120.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,750.00	700.00
4	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,750.00	660.00
5	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
Gross Labour Cost (S\$)			4,460.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >