

ASS. REC. BY:

REF:

AIC / 220124771kp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

19938h

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 59092

Yr Regn:

08, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Renault Latitude

C.C

1995

Colour

M. White / R

A/C:

Insured / Std / NI / NA

Sp. Reading

748899

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 002848

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S/Rim / STD A/Rim or

Tyre Size:

F:

195/215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Fin 789

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

13/11/22

D.O.I.

12/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/12 11 Pm @ 3550h Car

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fines

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5969L**AAD2211-092***Not Not hain**11 Pump & 355dr Max*

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

12 DEC 2022**SHC5969L**

VF1ABL15AUC282213

200303878K

RENAULT

LATITUDE

13/11/2022

SML8455B/AIG

03/08/2015

	PART
1	DOOR PANEL FRT LH
1	DOOR MOULDING FRT LH
1	DOOR HANDLE OUTER FRT LH
1	DOOR HANDLE MODULE FRT LH
1	DOOR REGULATOR FRT LH
1	DOOR REGULATOR MOTOR FRT LH
1	DOOR HINGE UPPER FRT LH
1	DOOR HINGE LOWER FRT LH
1	DOOR PANEL REAR LH
1	DOOR HANDLE OUTER REAR RH
1	DOOR HANDLE MODULE REAR RH
1	DOOR REGULATOR REAR LH
1	DOOR REGULATOR MOTOR REAR LH
1	DOOR HINGE UPPER REAR LH
1	DOOR HINGE LOWER REAR LH
1	ROCKER PANEL OUTER LH
1	FENDER PANEL REAR LH
1	WHEELARCH REAR LH

	LIST
\$	<i>Bz</i> 2,844.66 ✓
\$	<i>Sn</i> 100.50 X
\$	<i>Sn</i> 169.50 X
\$	<i>Sn</i> 133.40 X
\$	<i>Sn</i> 501.40 X
\$	<i>Sn</i> 758.10 X
\$	<i>n</i> 274.50 X
\$	<i>n</i> 300.55 X
\$	<i>Bz</i> 2,844.66 ✓
\$	<i>Sn</i> 42.10 X
\$	<i>Sn</i> 133.40 X
\$	<i>Sn</i> 450.60 X
\$	<i>Sn</i> 758.10 X
\$	<i>n</i> 241.60 X
\$	<i>n</i> 169.90 X
\$	<i>Bz</i> 1,184.99 ✓
\$	<i>n</i> 1,933.20 X
\$	<i>n</i> 275.40 X
TOTAL \$	13,116.56
10% \$	1,311.66
\$	11,804.90

Special Nett

2	DOOR TRIM CLIP	\$	<i>nn</i> 140.00 X
2	DOOR MOULDING CLIP	\$	<i>nn</i> 140.00 X
1	DOOR STICKER TRANSCAB	\$	<i>nn</i> 100.00 <i>60.00</i>

Trans-cab Auto Services Pte Ltd**AAD2211-092**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5969L

1 DOOR STICKER 65553333	\$	100.00	60501
1 DOOR STICKER CLASSIC	\$	100.00	15501
1 FENDER CLIP	\$	70.00	X
1 FENDER LINER CLIP	\$	65.00	X
TOTAL	\$	715.00	

TOTAL PARTS \$ 12,519.90**LABOUR**

To rust-proofing and apply undercoat of the affected areas.	\$	230.00	901
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	1201
Putty and spray painting of the affected portion.	\$	1,750.00	7001
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	1,750.00	6601
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To check steering geometry and computer wheel alignment	\$	220.00	X
TOTAL	\$	4,460.00	

Over All Total \$ 16,979.90**(LUMPSUM) Repair Days 05 Days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 878K

Vehicle Details

Vehicle No.: SHC5969L

Vehicle to be Exported: Yes

Intended Deregistration Date: 23 Nov 2022

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: M9R8839C002848

Chassis No.: VF1ABL15AUC282213

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 03 Aug 2015

First Registration Date: 03 Aug 2015

Transfer Count: 0

Actual ARF Paid: \$19,998.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 02 Aug 2023

PARF Rebate Amount: \$11,998.00

Intended COE Rebate Details

COE Expiry Date: 02 Aug 2023

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$50,236.00

COE Rebate Amount: \$4,355.00

Total Rebate Amount: \$16,353.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 23 Nov 2022

OK