

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012479/KYA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220058156
Claimant Vehicle No :	SNA5292U	Insured Vehicle No :	SKK6868K
Date of Loss:	10/12/2022	Nature of Claim:	TP
		Claim No:	3214004376SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA5292U	Engine No:	2Z2R2G91935
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU103091910
Reg. Date:	28/06/2021 (Man. Year: 2020)	Odometer:	155476 km
Colour:	Metallic Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 9 mm	Rear Left Side:	Firenza 9 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	Firenza 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,790.25	3,401.82	388.43	10.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	910.00	350.00	27.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,050.25	4,311.82	738.43	14.62
Approved Total (Overridden) (S\$)		3,450.00		
(S\$)	5,050.25	3,450.00	1,600.25	31.69
+ GST 7.00/7.00% (S\$)	353.52	241.50	112.02	31.69
Nett Amount (S\$)	5,403.77	3,691.50	1,712.27	31.69
+ Loss of Use (5.0 x S\$96.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,173.50		
Global Sum Settlement (S\$)		4,100.00		

INSPECTION

Date of Assignment:	13/12/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	13/12/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Estimated Period of Repair:	4.0 days	Singapore 568047

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Mtg Cracked	2,852.00 FL	*2,567.10 FL
2	1		*FRONT BUMPER	Buckled	665.00 FL	*526.00 FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	80.00 FL	*80.00 FL
4	1		*FRONT FENDER LH	Bent	988.00 FL	*988.00 FL
5	1		*FRONT FENDER HYBRID EMBLEM LH	Necessary	66.00 FL	*66.00 FL
6	1		*FRONT FENDER QUARTER GARNISH LH	Serviceable	94.00 FL	*- FL
7	1		*FRONT FENDER INNER SHIELD LH	Distorted	202.00 FL	*202.00 FL
8	1		*FRONT DOOR LH (NPA)	Repair	0.00 FL	*- FL
9	1		*FRONT RIM LH (NPA)	Repair	0.00 FL	*- FL
10	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
11	1		*FRONT FENDER INNER SHIELD CLIPS LH	Necessary	30.00 FS	*30.00 FS
					Sub Total (\$\$)	5,027.00 4,509.10
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,236.75 1,107.28
					Total Parts (\$\$)	3,790.25 3,401.82

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX & READJUST AT ACCIDENT AREAS	New	500.00	400.00
2	LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS	New	500.00	400.00
3	LABOUR CHARGES TO FRONT WHEEL ALIGNMENT & BALANCING	New	100.00	60.00
4	TO TUFF KOTE & UNDERSEAL MATERIALS	New	80.00	30.00
5	TO CHECK WIRING & ELECTRICAL SYSTEM	New	80.00	20.00
Gross Labour Cost (\$\$)			1,260.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >