

**COMFORT TRANSPORTATION PTE LTD****REPAIR ESTIMATE**Vehicle No. : *SHA 9191Y*

Date: 13/12/2022

Make : HYUNDAI

Insurance: INCOME

Model : I-40

MVA: MS. LOKE Y Y

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	REAR BUMPER COVER			\$ 553.00	<i>/CRA</i>
1	REAR BUMPER CLIPS			\$ 22.00	<i>XNN</i>
1	REAR BUMPER LOWER COVER			\$ 228.00	<i>?XSVC</i>
	<b>SUB TOTAL</b>			\$ 803.00	
	<b>LESS 20%</b>			\$ 160.60	
	<b>DISCOUNTED TOTAL</b>			<b>\$ 642.40</b>	
					Nett
					Nett
				\$ -	Nett
	<b>Labour Charge</b>				
	PANEL BEATING			\$ <del>300.00</del>	<i>280</i>
	SPRAY PAINTING CHARGE			\$ <del>300.00</del>	<i>250</i>
	REMOVE/REFIX REVERSE SENSOR			\$ <del>60.00</del>	<i>30</i>
	<b>TOTAL LABOUR</b>			<b>\$ 660.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$ 1,302.40</b>	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*NA2 LKK**13/12/2022 1615**L/S**2 Days**CHECK ITEM PHOTO)**AFTER REPAIR PHOTO)*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: