

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: BVS20/1237 Date: 21st Feb 2023

Our Ref: CS1/LIP22012483/Dqy3e2

M/s Liberty Insurance Pte Ltd

51 Club Street, #03-00 Liberty House Singapore 069428 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SDY 8187M

INSURED VEHICLE: XB 2780Z ACCIDENT DATE: 19/12/2020

We thank you for your instruction on 13/12/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SDY 8187M from M/s United Appraisal And Management Pte Ltd.
- b) Final Repair Bill of SDY 8187M from M/s Hiap Lek Automobile Trading.
- c) Singapore Accident Statement of Vehicles SDY 8187M.
- d) Colour damaged vehicle photographs of SDY 8187M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SDY 8187M

Make & Model : Mercedes Benz E200 Sedan Edition E (R18 LED)

Chassis Number : WDD2120342B228939

Date of Registration : 03 Dec 2015 Engine Capacity : 1991 cc

- 2. We recommend that the repairs of the entire damage require about <u>7 (Seven)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.