

ASS. REC. BY:

REF: 072 / 22012484/KP

Kenneth

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Optima

of 7182

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$257k

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 8-10 days Res.: Yes or No

Lum Sum: 1.21 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SNH 57756 Yr Regn: 09, 22

Type: MCAR / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or A1

Make: Tesla Model Y c.c. \_\_\_\_\_

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: LRWYHCF-SINC 46488

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/R/Im / STD / R/Im or

Tyre Size: F: 255/45R19

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front R/Bal. 0 mm

L/Bal. 0 mm

D.O.A. 8/12/22

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

& RT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	Tail pipe jammed, broken flat. All parts have to order from overseas.

Date/Time, File Pass to?  : Prell. Report  : Final Report

1) \_\_\_\_\_  
Date/Time, File Return to?

2) \_\_\_\_\_

Report Format :  
Lump Sum / I.B.I: (\$

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech Invs (\$ )  
 : Weekend (\$ )

Survey Fee:	_____
Transportation:	_____
S - RS. SI	_____
Fin. Ins	_____
Others	_____
TOTAL	_____



Date: 14/12/2022  
Vehicle No: SNH5775G  
Model: TESLA MODEL Y RWD  
Chassis: LRWYHCFS1NC464648 - 2022  
Reg. Year: 2022

*Not Authored*  
*Repair by paint*  
*8-9 days*

Third Party Insurer: CHINA TAIPING  
Third Party Veh No: SMW2339K  
Date of Accident: 08/12/2022  
Estimator: KIT  
Surveyor:

## ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	REAR BOOTLID	1		<i>Ry</i> \$1,219.63	✓
2	REAR BOOTLID "TESLA" EMBLEM	1		<i>rc</i> \$48.60	✓
3	REAR BOOTLID LAMP LH	1		\$177.57	?
4	REAR BOOTLID LAMP RH	1		<i>rc</i> \$177.57	X
5	REAR BOOTLID NUMBER PLATE LAMP LH	1		<i>rc</i> \$18.69	X
6	REAR BOOTLID NUMBER PLATE LAMP RH	1		<i>rc</i> \$18.69	X
7	REAR BOOTLID OUTER HANDLE WITH REVERSE CAMERA	1		<i>rc</i> \$121.50	X
8	REAR BOOTLID NUMBER PLATE GARNISH	1		\$4.67	?
9	REAR BOOTLID MECHANISM LOCK	1		<i>rc</i> \$54.21	✓
10	REAR BOOTLID MECHANISM LOCK COVER	1		\$5.61	?
11	REAR BOOTLID LOCK STRIKER	1		<i>rc</i> \$6.54	X
12	REAR BOOTLID INNER TRIM BOARD	1		\$177.57	?
13	REAR BOOTLID HINGE LH	1		<i>rc</i> \$33.64	X
14	REAR BOOTLID HINGE RH	1		<i>rc</i> \$33.64	X
15	REAR BOOTLID STRUT LH	1		\$88.79	?
16	REAR BOOTLID STRUT RH	1		\$39.25	?
17	REAR BOOTLID WEATHERSTRIP	1		\$93.20	?
18	REAR TAIL LAMP LH	1		\$280.37	?
19	REAR TAIL LAMP RH	1		<i>rc</i> \$280.37	X
20	REAR TAIL LAMP BRACKET LH	1		\$2.80	?
21	REAR TAIL LAMP BRACKET RH	1		<i>rc</i> \$2.80	X
22	REAR BUMPER	1		<i>Ry</i> \$836.45	✓
23	REAR BUMPER SIDE BRACKET LH	1		<i>Or</i> \$5.61	✓
24	REAR BUMPER SIDE BRACKET RH	1		<i>rc</i> \$5.61	X
25	REAR BUMPER CENTER BRACKET	1		\$8.41	?
26	REAR BUMPER PARKING SENSOR	4	\$158.88	\$635.52	?
27	REAR BUMPER PARKING SENSOR BRACKET	4	\$6.54	\$26.16	?
28	REAR BUMPER LOWER DIFFUSER	1		<i>Ry</i> \$308.41	✓
29	REAR BUMPER REFLECTOR LH	1		<i>rc</i> \$40.19	✓
30	REAR BUMPER REFLECTOR RH	1		<i>cm</i> \$40.19	✓
31	REAR BUMPER TOWING COVER	1		<i>rc</i> \$20.56	✓
32	REAR BUMPER UNDER COVER	1		<i>cm</i> \$252.34	✓
33	REAR BUMPER REINFORCEMENT	1		\$299.07	?
34	REAR END PANEL	1		\$495.33	?
35	REAR END PANEL LH	1		\$154.21	?
36	REAR END PANEL RH	1		<i>rc</i> \$154.21	X

**Head office**

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

8A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011





Date: 14/12/2022  
Vehicle No: SNH5775G  
Model: TESLA MODEL Y RWD  
Chassis: LRWYHCFS1NC464648 - 2022  
Reg.Year: 2022

Third Party Insurer: CHINA TAIPING  
Third Party Veh No: SMW2339K  
Date of Accident: 08/12/2022  
Estimator: KIT  
Surveyor:

37	REAR END PANEL TOP GARNISH	1		\$9.35	?
38	REAR FLOOR PANEL	1		\$897.20	?
39	REAR FLOOR PANEL SEAL	1		\$13.08	?
40	REAR FLOOR PANEL LUGGAGE COMPARTMENT	1		\$74.77	?
41	REAR FLOOR PANEL TOP CARD BOARD	1		\$45.79	?
42	REAR FENDER REFLECTOR LAMP LH	1		Sm \$40.19	X
43	REAR FENDER REFLECTOR LAMP RH	1		Sm \$40.19	X
44	REAR FENDER WHEEL ARCH GARNISH LH	1		Di \$65.42	✓
45	REAR FENDER WHEEL ARCH GARNISH RH	1		Sm \$65.42	X
46	REAR FENDER INNER SHIELD LH	1		Di \$177.57	✓
47	REAR FENDER INNER SHIELD RH	1		\$177.57	?
48	REAR FENDER INNER TRIM BOARD LH	1		\$74.77	?
49	REAR FENDER INNER TRIM BOARD RH	1		\$53.27	?
50	REAR FENDER LH	1		REPAIR	
51	REAR FENDER RH	1		REPAIR	
52	FRONT BONNET	1		R \$1,953.27	X
53	FRONT BONNET "TESLA" EMBLEM	1		Sm \$48.60	X
54	FRONT BONNET HINGE LH	1		R \$107.48	X
55	FRONT BONNET HINGE RH	1		R \$107.48	X
56	FRONT BONNET STRUT LH	1		R \$6.54	X
57	FRONT BONNET STRUT RH	1		R \$6.54	X
58	FRONT BONNET LOCK	1		R \$177.57	X
59	FRONT BONNET LOCK ACTUATOR	1		R \$107.48	X
60	FRONT BONNET LOCK STRIKER	1		R \$52.34	X
61	FRONT LUGGAGE COMPARTMENT	1		\$242.99	?
62	FRONT LUGGAGE COMPARTMENT REINFORCEMENT	1		\$29.91	?
63	FRONT LUGGAGE COMPARTMENT BRACKET	1		\$14.95	?
64	FRONT LUGGAGE COMPARTMENT SEAL	1		Sm \$15.89	X
65	FRONT HEADLAMP LH	1		\$1,308.41	?
66	FRONT HEADLAMP RH	1		Sm \$1,308.41	X
67	FRONT HEADLAMP LOWER BRACKET LH	1		\$7.48	?
68	FRONT HEADLAMP LOWER BRACKET RH	1		Sm \$7.48	X
69	FRONT HEADLAMP WIRE HARDNESS	1		Sm \$518.69	X
70	FRONT BUMPER	1		CM \$542.06	✓
71	FRONT BUMPER SIDE BRACKET LH	1		Di \$0.93	✓
72	FRONT BUMPER SIDE BRACKET RH	1		Sm \$0.93	X
73	FRONT BUMPER CENTER UPPER BRACKET LH	1		\$0.93	?
74	FRONT BUMPER CENTER UPPER BRACKET RH	1		\$0.93	?
75	FRONT BUMPER NUMBER PLATE GARNISH	1		Red \$5.61	✓

Head office

8 Kung Chong Road Singapore 150143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011





Date: 14/12/2022  
 Vehicle No: SNH5775G  
 Model: TESLA MODEL Y RWD  
 Chassis: LRWYHCFS1NC464648 - 2022  
 Reg.Year: 2022

Third Party Insurer: CHINA TAIPING  
 Third Party Veh No: SMW2339K  
 Date of Accident: 08/12/2022  
 Estimator: KIT  
 Surveyor:

76	FRONT BUMPER PARKING SENSOR	<i>Sn</i>	4	\$158.88	\$635.52	X
77	FRONT BUMPER PARKING SENSOR BRACKET		4	\$6.54	\$26.16	?
78	FRONT BUMPER SENSOR WIRE HARDNESS		1		<i>Sn</i> \$93.46	X
79	FRONT BUMPER SIDE GARNISH LH		1		\$6.54	?
80	FRONT BUMPER SIDE GARNISH RH		1		\$6.54	?
81	FRONT BUMPER LOWER GRILLE		1		<i>Sn</i> \$186.92	X
82	FRONT BUMPER UNDER COVER		1		<i>Sn</i> \$336.45	X
83	FRONT BUMPER SPONGE		1		\$46.73	?
84	FRONT BUMPER REINFORCEMENT		1		\$299.07	?
85	FRONT BUMPER REINFORCEMENT CRUSH CAN LH		1		\$60.75	?
86	FRONT BUMPER REINFORCEMENT CRUSH CAN RH		1		\$60.75	?
87	FRONT BUMPER LOWER REINFORCEMENT		1		<i>R</i> \$102.80	X
88	FRONT BUMPER LOWER CRUSH CAN LH		1		\$29.91	?
89	FRONT BUMPER LOWER CRUSH CAN RH		1		\$29.91	?
90	FRONT RADAR SENSOR		1		\$345.79	?
91	FRONT RADAR SENSOR BRACKET		1		\$6.54	?
92	FRONT RADAR SENSOR WIRE HARDNESS		1		<i>Sn</i> \$149.53	X
93	FRONT SUPPORT PANEL		1		\$158.88	?
94	FRONT SUPPORT PANEL BRACKET		1		\$14.95	?
95	FRONT AIR GRILLE SHUTTER ASSY		1		\$149.53	?
96	FRONT FENDER LH		1		<i>R</i> \$495.33	X
97	FRONT FENDER RH		1		<i>R</i> \$495.33	X
98	FRONT FENDER SUPPORT LH		1		<i>R</i> \$13.08	X
99	FRONT FENDER SUPPORT RH		1		<i>R</i> \$13.08	X
100	FRONT DOOR GLASS LH		1	<i>(CRASH)</i>	\$355.14	?
101	FRONT SAFETY SEAT BELT LH		1		<i>Tn</i> \$355.14	✓
102	FRONT SAFETY SEAT BELT RH		1		<i>Tn</i> \$355.14	✓
103	REAR SAFETY SEAT BELT LH		1		<i>Tn</i> \$45.79	✓
104	REAR SAFETY SEAT BELT RH		1		<i>Tn</i> \$45.79	✓
105	REAR SAFETY SEAT BELT CENTRE		1		\$45.79	?
106	BATTERY PYRO DISCONNECTOR ASSY		1		\$27.10	?
107	RESTRAINT CONTROL MODULE		1		<i>Sn</i> \$560.75	✓
108	REAR BLE ASSEMBLY		1		\$20.56	?
					SUB TOTAL	\$20,050.22
					LESS 10%	\$2,005.02
					PARTS TOTAL	\$18,045.20



Date: 14/12/2022  
 Vehicle No: SNH5775G  
 Model: TESLA MODEL Y RWD  
 Chassis: LRWYHCFS1NC464648 - 2022  
 Reg.Year: 2022

Third Party Insurer: CHINA TAIPING  
 Third Party Veh No: SMW2339K  
 Date of Accident: 08/12/2022  
 Estimator: KIT  
 Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR NUMBER PLATE WITH HOLDER	1		<i>Ne</i> \$50.00
2	REAR BOOTLID INNER TRIM CLIPS	1		<i>Ne</i> \$30.00
3	REAR BUMPER CLIPS	1		<i>Ne</i> \$50.00
4	REAR END PANEL JOINT SEALANT	1		\$60.00
5	REAR END PANEL TOP GARNISH CLIPS	1		\$30.00
6	REAR FENDER INNER SHIELD CLIPS LH	1		<i>Ne</i> \$30.00
7	REAR FENDER INNER SHIELD CLIPS RH	1		\$30.00
8	FRONT BUMPER CLIPS	1		<i>Ne</i> \$50.00
9	FRONT NUMBER PLATE WITH HOLDER	1		<i>Ne</i> \$50.00
10	FRONT DOOR GLASS SOLAR FILM LH	1		\$150.00
11	WRAPPING FOR ACCIDENT AREAS	1	( <i>Kit</i> )	\$2,000.00
<b>S/N TOTAL</b>				<b>\$2,530.00</b>

*45in*  
*✓*  
*✓*  
*?*  
*?*  
*✓*  
*?*  
*✓*  
*45in*  
*?*  
*?*

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS	\$2,200.00	<i>?</i>
LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS	\$2,200.00	<i>800</i>
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS.	\$150.00	<i>1200</i>
TO REMOVE & REINSTALL REAR BOOTLID MECHANISM BACK TO ORIGINAL FUNCTIONS.	\$100.00	<i>600</i>
LABOUR CHARGES TO REMOVE & REPLACE REAR PARKING SENSOR.	\$100.00	<i>600</i>
LABOUR CHARGES TO REMOVE & REPLACE FRONT PARKING SENSOR.	\$100.00	<i>600</i>
TO DAIGNOSIS FAULT CODE & RESET MEMORY.	\$300.00	<i>2000</i>
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$300.00	<i>500</i>
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$120.00	<i>?</i>

KIT

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**LABOUR TOTAL** \$5,570.00

---

**TOTAL** \$26,145.20

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Branch (Motor Insurance Claims)



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 09/12/2022 23:25 (SGT)  
Reported by ..... Driver  
Date of Accident ..... 08/12/2022 11:05 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... PIE TOWARDS CHANGI AIRPORT BEFORE ENG NEO AVE EXIT  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SNH5775G

### INSURED/POLICYHOLDER

Is company? ..... Yes  
Name Of Registered Owner ..... MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE PTE. LTD  
Company Reg No ..... 199803778Z  
Email Address ..... derrick.lee@mercedes-benz.com  
Mobile Phone No ..... (Phone) +65-68498118  
Alternative Phone No ..... -

### VEHICLE PARTICULARS

Manufacturer ..... Tesla  
Model ..... MODEL Y RWD  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private hire  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 0

### INSURANCE COMPANY

Name of Insurance Company ..... AIG Asia Pacific Insurance Pte. Ltd.  
Policy Number / Cover Note Number ..... 999995580

### DRIVER

Name of Driver ..... LOH CHENG TUAN MALCOLM  
NRIC No ..... S1813915D  
Date Of Birth ..... 20/12/1967



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report promptly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that :  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


*[Signature]* 8/12/2022

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**



PIE