

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD
 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

Contact : 97314140

TP AYA.
 Xiao Tony.

TAX INVOICE

Repair Code : CLM17519

Date in : 12/12/2022

Vehicle Num. : SMQ8259A

Model : TOYOTA SIENTA HYBRID 7-SEATER 1.5X CVT

Chassis/Eng# : NHP1707181269/1NZR808197

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Delnd</i>	1	344.10	✓ 344.10
REAR BUMPER CENTER PROTECTOR (BLACK) <i>lt</i>	1	205.40	✓ 205.40
REAR BUMPER REFLECTOR GARNISH L/R <i>new</i>	2	65.00	✗ 130.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	108.70	✗ 217.40
REAR BUMPER TOW HOOK COVER <i>new</i>	1	30.40	✗ 30.40
REAR END PANEL <i>Repair</i>	1	469.60	✗ 469.60
REAR END PANEL INNER ANTENNA SENSOR <i>crushed</i>	1	78.00	✓ 78.00
REAR END PANEL INNER TOP GARNISH <i>new</i>	1	159.20	✗ 159.20
REAR TAILGATE <i>Delnd</i>	1	1221.80	✓ 1,221.80
REAR TAILGATE 'HYBRID' EMBLEM <i>new</i>	1	56.30	✓ 56.30
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	73.10	✓ 73.10
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	30.10	✗ 60.20
REAR TAILGATE MECHANISM LOCK <i>Delnd</i>	1	506.10	389 506.10
REAR TAILGATE WEATHER STRIP <i>new</i>	1	402.50	✗ 402.50
REAR TAILGATE WINDSCREEN MOULDING <i>new</i>	1	38.50	✓ 38.50

2406.20
 1804.65

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TWINCAR LEASING PTE LTD
 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

Contact : 97314140

TAX INVOICE

Repair Code : CLM17519

Date in : 12/12/2022

Vehicle Num. : SMQ8259A

Model : TOYOTA SIENTA HYBRID 7-SEATER 1.5X CVT

Chassis/Eng# : NHP1707181269/1NZR808197

		Subtotal before discount	3,992.60
Percentage discount	25%		998.15
		Sub-total 1	2,994.45
REAR BUMPER CLIPS - SET	New	1	80.00 80.00
REAR BUMPER REVERSE SENSOR - SET	Damaged	1	280.00 280.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	Not new	1	40.00 40.00
REAR TAILGATE INNER WEATHER STRIP SEAL	Not in	1	100.00 100.00
REAR TAILGATE WINDSCREEN SEALANT	New	1	80.00 80.00
		Subtotal before discount	580.00
Percentage discount	0%		0.00
		Sub-total 2	580.00
		Parts-total	3,574.45

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total 2,190.00
 Parts & Labour Total 5,764.45

total: 3154.65
 h/s: 2.5K.✓