

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Faiz Rosli

Date: 20 Feb 2023

Preliminary Advice

Insured Vehicle No	: SMJ173C	Accident Date	: 27/11/2022
TP Vehicle No	: SMP1337J	Assignment Date	: 13/12/2022
Make	: TOYOTA NOAH	Est. Duration of Repair	: 4
Date of Inspection	: 14/12/2022		
Inspection At	: LIAN HER MOTORS (ANG MO KIO) BLK 5038, ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,210.53
Revised Amount	:S\$	5,301.11
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,301.11
Lump Sum Repair	:S\$	4,200.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.