



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				CS3/CTI22001887/Twp3-1
CHINA TAIPING INSURANCE (S) PTE LTD		Ref: <del>000/CTI22001887/Twp3</del>		
3 ANSON ROAD #16-00		Date: <del>20/02/2022</del> 12/12/2022		
SPRINGLEAF TOWERSINGAPORE 079909		Code: CTI		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	GV 3969L	Veh. Inspected	JTF 8403	
Policy No.		Coverage (\$)	0.00	
Claim No.	SNM22D201034/C02/GV3969L/CHEESC	Excess (\$)	0.00	
Assign From	CHEE SO CHOW	Assign Date	<del>20/02/2022</del> 12/12/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	10/02/2022	Inspection Date	28/02/2022	
Survey held at	TUCK LIFE PTE LTD 25 KAKI BUKIT ROAD 4# 01-68 SYNERGY@ KB SINGAPORE 417800			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				