

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMY 27034

at Workshop no/s KAH MOTOR

of 255, BLANCK RD

Insured: HLA

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 185K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMY 27034 Yr Regn: 2021 / FEB

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA 004J542-4BX S/R.c. 2356

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 00303 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMRC 1890LC263885

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / ST / AD / Rim or

Tyre Size: F: 215/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 10/2/22

Survey held at KAH MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 116K

Date/Time, File Pass to?

☐

: Prefl. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

____ S + RS ____ SI

Photos

Others

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

Report Format : _____

Lump Sum / R / S



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : HL ASSURANCE PTE. LTD
11 KEPPEL ROAD
#11-01 ABI PLAZA
SINGAPORE 089057
Registration No : SMY2703G
Chassis No : JHMRC1890LC203885
Model : ODYSSEY 2.4 EXV-S 20YM (EURO 6)
Owner's Name : HOE MEI YING
Ins Policy No. :
Date of Accident : 10/12/2022

Document No. : SQT22003673 **Page** 1
Date : 12. Dec 2022
Customer No. : WZH001
Svc Advisor : NG SIN HAI
Engine No : K24W72501501
Date | Time : 12. Dec 2022 6:22:39 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N) X	1	45.00		45.00	3.15	48.15
73211-T6A-Q02	GLASS SET,RR.WINDSHIELD X	1	1082.20	25	811.65	56.82	868.47
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE new	2	19.20	25	28.80	2.02	30.82
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER m	1	18.10	25	13.57	0.95	14.52
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER m	1	18.10	25	13.57	0.95	14.52
73221-SR4-000	SPACERRR.W/SHIELD m	4	4.20	25	12.60	0.88	13.48
73225-TM8-000	RUBBER A WINDSHIELD DAM m	1	3.90	25	2.92	0.20	3.12
73226-SZW-000	DAMPERSTD 5X5 m	1	9.10	25	6.82	0.48	7.30
76711-T6A-003	CAPPIVOT m	1	5.20	25	3.90	0.27	4.17
BO-WS-SEALANT	WINDSCREEN SEALANT (N) m	2	60.00		120.00	8.40	128.40
68100-T6A-Q10ZZ	TAILGATE COMP sh	1	1146.20	25	859.65	60.18	919.83
74440-T6A-003	WEATHERSTRIPTAILGATE X	1	125.70	25	94.27	6.60	100.87
75701-T6A-000	EMBLEMH m	1	28.20	25	21.15	1.48	22.63
75722-T6A-901	EMBLEM,RR. m	1	33.20	25	24.90	1.74	26.64
04715-T6A-N10ZZ	FACE ASSY,RR.BUMPER de	1	562.00	25	421.50	29.51	451.01
71593-T6A-003	SPACERR.RR.BUMPER SIDE m	1	20.40	25	15.30	1.07	16.37
71598-T6A-003	SPACERL.RR.BUMPER SIDE m	1	20.40	25	15.30	1.07	16.37
91505-TM8-003	CLIP,BUMPER m	7	2.30	25	12.07	0.84	12.91
66100-T6A-Q01ZZ	PANEL COMP,REAR ?	1	493.20	25	369.90	25.89	395.79

Printed on 12/12/2022 6:38:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : HL ASSURANCE PTE. LTD
 11 KEPPEL ROAD
 #11-01 ABI PLAZA
 SINGAPORE 089057

Registration No : SMY2703G

Chassis No : JHMRC1890LC203885

Model : ODYSSEY 2.4 EXV-S 20YM (EURO 6)

Owner's Name : HOE MEI YING

Ins Policy No. :

Date of Accident : 10/12/2022

Document No. : SQT22003673 Page 2

Date : 12. Dec 2022

Customer No. : WZH001

Svc Advisor : NG SIN HAI

Engine No : K24W72501501

Date | Time : 12. Dec 2022 6:22:39 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
04656-T6A-310ZZ	PAN SET,3RD SEAT X	1	361.70	25	271.27	18.99	290.26
34150-T6A-J51	LIGHT ASSY,R.LID X	1	413.40	25	310.05	21.70	331.75
34155-T6A-J51	LIGHT ASSY,L.LID X	1	381.90	25	286.42	20.05	306.47
33500-T6A-J51	LIGHT ASSY,R.TAIL X	1	897.20	25	672.90	47.10	720.00
33550-T6A-J51	LIGHT ASSY,L.TAIL X	1	897.20	25	672.90	47.10	720.00
39683-T6A-N11ZB	RETAINER,PARKING ?	4	44.70	25	134.10	9.39	143.49
39680-T0A-R12A4	SENSOR ASSY,PARKING BACK SENSOR ?	4	286.70	25	860.10	60.21	920.31
84640-T6A-003ZA	LINING ASSYRR.PANEL X	1	110.90	25	83.17	5.82	88.99
33505-SLJ-013	REFLECTOR ASSYR.RR. ?	1	48.50	25	36.37	2.55	38.92
33555-SLJ-013	REFLECTOR ASSYL.RR. X	1	48.50	25	36.37	2.55	38.92
71502-T6A-003ZE	FACER.RR.BUMPER GARNISH X	1	84.70	25	63.52	4.45	67.97
71507-T6A-003ZD	FACEL.RR.BUMPER GARNISH X	1	84.70	25	63.52	4.45	67.97
71512-T6A-901ZF	SPOILER ASSY,R.RR. X	1	105.60	25	79.20	5.54	84.74
71517-T6A-901ZF	SPOILER ASSY,L.RR. X	1	105.60	25	79.20	5.54	84.74
74800-TF0-J02	LOCKTAILGATE X	1	198.40	25	148.80	10.42	159.22
74890-T6A-N11ZG	GARNISH ASSY,RR.LICEION LID X	1	175.80	25	131.85	9.23	141.08
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN cut	1	187.90	25	140.92	9.86	150.78
63320-T6A-300ZZ	GUTTER COMPR.RR.PILLAR X	1	140.90	25	105.67	7.40	113.07
63720-T6A-300ZZ	GUTTER COMPL.RR.PILLAR X	1	140.90	25	105.67	7.40	113.07
72585-T6A-000ZZ	COVER COMPL.SLIDE DR CTR RAIL X	1	176.20	25	132.15	9.25	141.40
90001-T6A-003	BOLT TAIL LIGHT X	1	4.00	25	3.00	0.21	3.21
38387-SLE-003	ANTENNA ASSY,L.RR. ?	1	64.80	25	48.60	3.40	52.00
74940-TR0-003	BUZZER ASSYSMART ?	1	64.30	25	48.22	3.38	51.60
72841-SH3-315	OILSHEET X	1	43.50	25	32.62	2.28	34.90
74827-T0A-A00	STOPPERTAILGATE X	1	3.80	25	2.85	0.20	3.05
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER X	1	220.80	25	165.60	11.59	177.19
84435-T6A-J01ZA	GARNISH ASSYR.TAILGATE SIDE X	1	44.20	25	33.15	2.32	35.47
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL X	1	11.50	25	8.62	0.60	9.22
84485-T6A-J01ZA	GARNISH ASSYL.TAILGATE SIDE X	1	44.20	25	33.15	2.32	35.47

Printed on 12/12/2022 6:38:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : HL ASSURANCE PTE. LTD
11 KEPPEL ROAD
#11-01 ABI PLAZA
SINGAPORE 089057
Registration No : SMY2703G
Chassis No : JHMRC1890LC203885
Model : ODYSSEY 2.4 EXV-S 20YM (EURO 6)
Owner's Name : HOE MEI YING
Ins Policy No. :
Date of Accident : 10/12/2022

Document No. : SQT22003673
Date : 12. Dec 2022
Customer No. : WZH001
Svc Advisor : NG SIN HAI
Engine No : K24W72501501
Date | Time : 12. Dec 2022 6:22:39 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
84615-T6A-N73ZB	LINING COMP,R.RR.SIDGATE X	1	785.90	25	589.42	41.26	630.68
84643-T6A-Q01ZA	COMP LIDTOOL X	1	65.70	25	49.27	3.45	52.72
84665-T6A-N72ZB	LINING COMP,L.RR.SIDE X	1	755.10	25	566.32	39.64	605.96
Sum Item					8887.84	622.15	9,509.99
BOSUN	SUNDRIES	1	110.00	30	110.00	7.70	117.70
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00		250.00	17.50	267.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	250.00		250.00	17.50	267.50
BOJSE	BODY JOINT SEALANT TAILGATE	1	120.00	7/100	120.00	8.40	128.40
BOJSE	BODY JOINT SEALANT REAR PANEL	1	120.00	X	120.00	8.40	128.40
BOJSE	BODY JOINT SEALANT FLOOR PANEL	1	120.00	X	120.00	8.40	128.40
BOBC	BODY UNDERSIDE COATING (N)	1	520.00	X	520.00	36.40	556.40
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	520.00	X	520.00	36.40	556.40
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	650.00	580	650.00	45.50	695.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	650.00	560	650.00	45.50	695.50
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	650.00	X	650.00	45.50	695.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50
BODAMKIT	WINDSCREEN DAM KIT.	1	120.00		120.00	8.40	128.40
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	45.50	695.50
BKRP02B	CUT & RENEW RR FLOOR PANEL.STRAIGHTEN FENDERS ALIG	1	4000.00	1300	4000.00	280.00	4280.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3150.00	1040	3150.00	220.50	3370.50
BOSUN	REMOVE AND RE-INSTALL TAILGATE SPOILER	1	560.00	480	560.00	39.20	599.20
Sum Labor					13090.00	916.30	14,006.30

Survey By

Date & Time

Total Amount 21,977.84 1,538.45 23,516.29

Printed on 12/12/2022 6:38:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : HL ASSURANCE PTE. LTD
11 KEPPEL ROAD
#11-01 ABI PLAZA
SINGAPORE 089057
Registration No : SMY2703G
Chassis No : JHMRC1890LC203885
Model : ODYSSEY 2.4 EXV-S 20YM (EURO 6)
Owner's Name : HOE MEI YING
Ins Policy No. :
Date of Accident : 10/12/2022

Document No. : SQT22003673 **Page** 4
Date : 12. Dec 2022
Customer No. : WZH001
Svc Advisor : NG SIN HAI
Engine No : K24W72501501
Date | Time : 12. Dec 2022 6:22:39 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
Excess							
Status							
Signature							

Total (Inclusive of GST)

23,516.29

Pen

Repair
4p 9000068
5 days
12/12/22 @ 1520
Reg before paint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 12/12/2022 6:38:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC

Owner ID: 086C

Vehicle No.: SMY2703G

Vehicle to be Exported: No

Intended Deregistration Date: 20 Dec 2022

Vehicle Make: HONDA

Vehicle Model: ODYSSEY 2.4 EXV-S CVT SR

Primary Colour: White

Manufacturing Year: 2020

Engine No.: K24W72501501

Chassis No.: JHMRC1890LC203885

Maximum Power Output: 129.0 kW (172 bhp)

Open Market Value: \$33,022.00

Original Registration Date: 25 Feb 2021

First Registration Date: 25 Feb 2021

Transfer Count: 0

Actual ARF Paid: \$38,231.00

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 24 Feb 2031

PARF Rebate Amount: \$28,673.00

COE Expiry Date: 24 Feb 2031

COE Category: E - Open - all except motorcycle

COE Period(Years): 10

QP Paid: \$49,489.00

COE Rebate Amount: \$40,075.00

Total Rebate Amount: \$68,748.00

The information contained herein is correct as at 20 Dec 2022

OK

Honda Odyssey 2.4A EXV-S Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map

AN AWARD-WINNING PREMIER AUTOMOTIVE HOUSE



Price	\$197,800		
Depreciation ⓘ	\$20,280 /yr View models with similar depre	Reg Date	20-Sep-2021 (8yrs 8mths 30days COE left)
Mileage	3,568 km (2.9k /yr)	Manufactured ⓘ	2021
Road Tax ⓘ	\$1,630 /yr	Transmission	Auto
Dereg Value ⓘ	\$85,268 as of today (change)	OMV ⓘ	\$34,735
COE ⓘ	\$62,600	ARF ⓘ	\$40,629
Engine Cap	2,356 cc	Power	129.0 kW (172 bhp)
Curb Weight ⓘ	1,884 kg	No. of Owners	1