

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/1115/2022/EQ
DATE : 13-Dec-22
WIP : 54527

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/12/2022

YOUR INSURED VEH NO : SJK 8523 D

China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Attn: Motor Claims Dept

OWNER'S NAME : MS LIM MUI PENG
ADDRESS : BLK 55 HUME AVENUE
#07-06
SINGAPORE 598752
TELEPHONE : HP +65 96248735
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO :
VEHICLE NO : **SDK 1237 Y**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 27/4/2019
ENGINE NO : CVK 078768
CHASSIS NO : WAUZZZF54KA036756
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Dec-22
PLACE OF ACCIDENT : BASEMENT CARPARK, PARC PALAIS, NEAR BLK 55,
HUME AVE S(598752)

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDK 1237 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	✓
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	800 ✓
4	TO RESPRAY FRONT BUMPER.	\$	1,000.00	800 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 3,272.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDK 1237 Y

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Deformed</i>	1	\$ 2,493.00	<i>✓</i>	
2	FRONT BUMPER FIXING PARTS <i>MC</i>	1	\$ 425.00	<i>+</i>	
3	FRONT BUMPER SECURING STRIP - LH / RH <i>? MN</i>	2	\$ 79.00	<i>? X</i>	
4	FRONT BUMPER GRILLE - CENTER <i>MC</i>	1	\$ 219.00	<i>+</i>	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>MC</i>	1	\$ 254.00	<i>+</i>	
6	FRONT BUMPER AIR GUIDE - LH <i>MC</i>	1	\$ 72.00	<i>+</i>	
7	RADIATOR GRILLE <i>Xloc MC</i>	1	\$ 2,576.00	<i>+</i>	
8	FRONT PARKING AID SENSOR SUPPORT - LH / RH <i>MC</i>	2	\$ 116.00	<i>+</i>	
9	RADIATOR GRILLE COVER - UPPER <i>MC</i>	1	\$ 209.00	<i>+</i>	
10	FRONT BUMPER AIR GUIDE GRILLE - LH <i>MC</i>	1	\$ 529.00	<i>+</i>	
11	FRONT BUMPER FOAM FILLER PIECE <i>? MN</i>	1	\$ 139.00	<i>? X</i>	
12	FRONT BUMPER REINFORCEMENT BEAM <i>MC</i>	1	\$ 899.00	<i>+</i>	
13	FRONT BUMPER GUIDE SECTION - LH <i>Xloc MC</i>	1	\$ 41.00	<i>+</i>	
14	FRONT BUMPER TOP COVER <i>MC</i>	1	\$ 143.00	<i>+</i>	
15	CAUTION SIGN STICKER <i>MC</i>	1	\$ 16.00	<i>+</i>	
16	AIR CONDITIONER STICKER <i>MC</i>	1	\$ 9.00	<i>+</i>	
17	LOCK CARRIER BRACKET <i>MC</i>	1	\$ 154.00	<i>+</i>	
18	FRONT BUMPER SUPPORT - LH / RH <i>MC</i>	2	\$ 64.00	<i>+</i>	
19	HORN HIGH TONE - LH <i>MC</i>	1	\$ 134.00	<i>+</i>	
20	HORN BRACKET - LH <i>MC</i>	1	\$ 33.00	<i>+</i>	
SUB TOTAL SPARE PARTS		:	\$ 8,604.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDK 1237 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SENSOR - INNER / OUTER <i>2 m</i>	2	\$ 532.00	<i>f</i>
22	FRONT PARKING AID SEAL RING	4	\$ 10.00	<i>f</i>
23	HEADLIGHT - LH <i>ct</i>	1	\$ 8,416.00	<i>✓</i>
24	LIFT CYLINDER - LH <i>? nn</i>	1	\$ 217.00	<i>? X</i>
25	LIFT CYLINDER BRACKET - LH <i>Ne n</i>	1	\$ 17.00	<i>+</i>
26	LIFT CYLINDER CORRUGATED PIPE <i>Ne n</i>	1	\$ 100.00	<i>x</i>
27	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	<i>x</i>
28	RADIATOR AIR GUIDE - LH / RH INNER	2	\$ 72.00	<i>+</i>
29	RADIATOR AIR GUIDE - LH / RH OUTER	2	\$ 38.00	<i>+</i>
30	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 44.00	<i>+</i>
31	FRONT NO PLATE <i>Ne n</i>	S/N	\$ 60.00	<i>+</i>
32	SUNDRIES <i>? nn</i>		\$ 400.00	<i>? X</i>
TOTAL SPARE PARTS		:	\$ 18,531.00	
TOTAL LABOUR CHARGES		:	\$ 3,272.00	
GRAND TOTAL		:	\$ 21,803.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lg*
SURVEYED DATE : *14/12/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT