


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: KIA CERATO
Engine/Chassis No.: KNAF1416MK5031228
Date of accident: 19.11.22
Damaged area: Front & Rear

Date: 14/12/2022
Claim Type: TP
VRN: SJQ1938E

Not Authorized
L1 Rm 83500
McCurry After Paint
4 days



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Bonnet	1	\$ 1,283.00	\$ 1,283.00	X
2	Bonnet lock	1	\$ 239.00	\$ 239.00	X
3	Bonnet bottom lock assy	1	\$ 58.00	\$ 58.00	X
4	Bonnet lock sensor	1	\$ 139.00	\$ 139.00	X
5	Headlamp	2	\$ 1,896.00	\$ 3,792.00	X
6	Headlamp lower bracket	2	\$ 68.00	\$ 136.00	X
7	Front bumper 083	1	\$ 1,086.00	\$ 1,086.00	✓
8	Front bumper lower deflector lip	1	\$ 479.00	\$ 479.00	X
9	Front bumper "KIA" logo	1	\$ 76.00	\$ 76.00	✓
10	Front bumper side retainer	2	\$ 98.00	\$ 196.00	X
11	Front bumper lower bracket	2	\$ 44.00	\$ 88.00	X
12	Front bumper grille	1	\$ 457.00	\$ 457.00	X
13	Front bumper grille chrome trim upper	1	\$ 189.00	\$ 189.00	✓
14	Front bumper lower grille	1	\$ 194.00	\$ 194.00	X
15	Front bumper lower grille bracket	2	\$ 35.00	\$ 70.00	X
16	Fog lamp	2	\$ 422.00	\$ 844.00	X
17	Fog lamp garnish	2	\$ 189.00	\$ 378.00	X
18	Front bumper tow cap	1	\$ 58.00	\$ 58.00	X
19	Front bumper sponge	1	\$ 178.00	\$ 178.00	X
20	Front bumper reinforcement 495	1	\$ 563.00	\$ 563.00	✓
21	Front support assy	1	\$ 683.00	\$ 683.00	X
22	Front support assy top garnish	1	\$ 339.00	\$ 339.00	X
23	Rear bumper 652	1	\$ 1,095.00	\$ 1,095.00	✓
24	Rear bumper lower 285	1	\$ 744.00	\$ 744.00	✓
25	Rear bumper signal lamp garnish	2	\$ 268.00	\$ 536.00	X
26	Rear bumper signal lamp	2	\$ 459.00	\$ 918.00	X
27	Rear bumper side retainer	2	\$ 48.00	\$ 96.00	X
28	Rear bumper reinforcement 388	1	\$ 715.00	\$ 715.00	✓
29	Rear bumper reinforcement side bracket C163	2	\$ 211.00	\$ 422.00	✓
30	Rear bumper sponge	1	\$ 251.00	\$ 251.00	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

31	Rear compartment top board	Per 1	\$ 223.00	\$ 223.00	X
32	End panel	Per 1	\$ 499.00	\$ 499.00	X
33	End panel top garnish	Per 1	\$ 223.00	\$ 223.00	X
34	Rear bumper reinforcement support bracket	Per 5	\$ 32.00	\$ 160.00	X
Subtotal				\$ 17,407.00	
List discount				10.00%	
Total				\$ 15,666.30	

Special nett items					
No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Bonnet insulator clips	nn 10	\$ 5.50	\$ 55.00	X
2	Front bumper clips	nn 12	\$ 5.50	\$ 66.00	—
3	Engine under cowlings clips	nn 8	\$ 5.50	\$ 44.00	X
4	Front licence plate & frame	Per 1	\$ 55.00	\$ 55.00	455m
5	Rear bumper clips	nn 12	\$ 5.50	\$ 66.00	—
6	End panel sealant	nn 1	\$ 80.00	\$ 80.00	X
7	End panel top garnish clips	nn 8	\$ 5.50	\$ 44.00	X
8	Reverse sensor	Per 1	\$ 280.00	\$ 280.00	260m
9	Sundries	nn 1	\$ 50.00	\$ 50.00	X
Total				\$ 740.00	

Labour				
No.	Description	Work unit	Amount	
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	8	\$ 1,600.00	600
2	To disconnect wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.5	\$ 100.00	30
3	Supply spray paint material and necessary items to respray affected area / panel.	7	\$ 1,400.00	800
4	To rust proof all affected portions after repair.	0.5	\$ 100.00	X
Total labour			\$ 3,200.00	

Estimate Grand Total	\$ 19,606.30
----------------------	--------------

