



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22012508/Dwy3e2 Date: 16/03/2023 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SFB 6040M	<b>Veh. Inspected</b>	SHC 2334M
	<b>Policy No.</b>	SD22V08715/VPE/R00	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	AVS22/3500	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	TED SEAH	<b>Assign Date</b>	14/12/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	HYUNDAI I40	<b>c.c</b>	1685
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
	<b>Chassis No.</b>	KMHLB41UMHU098648	<b>Colour</b>	BLUE
	<b>Odometer</b>	839969 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	205/60 R16	GITI	5 mm
	<b>L/H Front Tyre</b>	205/60 R16	GITI	5 mm
	<b>R/H Rear Tyre</b>	205/60 R16	GITI	5 mm
	<b>L/H Rear Tyre</b>	205/60 R16	GITI	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	13/12/2022	<b>Inspection Date</b>	14/12/2022
	<b>Survey held at</b>	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
<b>5a. Remarks</b>				
	A)REGISTRATION DATE: 13 DEC 2017 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>	