

JEC AUTO SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6, #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

TP Chua
Xiao Chn.

Vehicle No. GBC597E

NISSAN CABSTAR

JN1SC2F24Z0801690

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	FRONT BUMPER <i>Distorted</i>		698.20	✓
2	FRONT BUMPER REINFORCEMENT <i>Best.</i>		521.40	✓
3	FRONT BUMPER FOG LAMP COVER @45.20 <i>Missing</i>		90.40	✓
4	FRONT GRILLE <i>Cracked</i>		438.40	✓
5	FRONT GRILLE LOGO <i>new</i>		75.90	✓
6	FRONT PANEL <i>Distorted</i>		1412.70	✓
7	CABSTAR EMBLEM <i>new</i>		55.20	✓
8	HEADLAMP @518.50 <i>smashed</i>		1037.00	✓
9	HEADLAMP LOWER GARNISH @81.30 <i>Smashed</i>		162.60	✓
10	FRONT CORNER PANEL @389.90 <i>Bruised</i>		779.80	✓
11	FRONT WIPER PANEL <i>Distorted</i>		567.80	✓
12	FRONT WINDSCREEN GLASS <i>Smashed</i>		1095.30	✓
13	FRONT WINDSCREEN GLASS MOULDING <i>new</i>		172.50	✓
14	FRONT WINDSCREEN PILLAR @845.30 <i>Bruised</i>		1690.60	✓
15	WIPER MOTOR <i>new</i>		583.20	+
16	WIPER MOTOR LINKAGE <i>new</i>		241.80	+
17	WIPER ARM @56.80 <i>Distorted</i>		113.60	✓
18	WIPER NOZZLE @45.10 <i>Distorted</i>		90.20	✓
19	FRONT WING MIRROR (RECTANGULAR)@164.10 <i>Missing</i>		328.20	✓
20	FRONT LH WING MIRROR (CIRCULAR) <i>Missing</i>		103.20	✓
21	FRONT WING MIRROR STAND @206.5 <i>Missing, Distorted</i>		413.00	✓
22	FRONT WING MIRROR STAND COVER @121.20 <i>Missing</i>		242.20	✓
23	ROOF PANEL <i>Repair</i>		1498.30	+
24	ROOF PANEL INNER TRIM <i>new</i>		690.60	+
25	FRONT CHASSIS CROSSMEMBER <i>Repair</i>		1168.40	+
26	CABIN HINGE @383.60 <i>Best</i>		767.20	✓
27	CABIN RUBBER MOUNTING @58.20 <i>Distorted</i>		116.40	✓
28	CABIN HINGE TORSION BAR <i>Best</i>		1665.40	✓
29	CABIN HINGE TORSION BAR SHAFT <i>new</i>		284.90	+
30	AIR CON CONDENSER <i>Distorted</i>		641.40	✓
31	AIR CON CONDENSER FRAME <i>Best</i>		145.40	✓
32	AIR CON CONDENSER FAN ASSY <i>new</i>		354.40	+
33	AIR CON SUCTION PIPE <i>new</i>		276.90	+
34	AIR CON DISCHARGE PIPE <i>new</i>		294.50	+
35	AIR CON LIQUID PIPE <i>new</i>		210.90	+
36	INTERCOOLER <i>new</i>		1782.80	+
37	INTERCOOLER PIPE <i>Dented</i>		289.60	✓
38	RADIATOR <i>Dented</i>		988.50	✓
39	RADIATOR FAN BLADE <i>Cracked</i>		166.10	✓
40	RADIATOR FAN COWLING <i>Cracked</i>		136.80	✓
41	RADIATOR FAN CLUTCH <i>new</i>		352.80	✓
42	ENGINE MOUNTING @290.40 <i>tom</i>		580.80	✓
43	BRAKE MASTER PUMP <i>new</i>		353.60	+
44	BRAKE BOOSTER PUMP <i>new</i>		1276.10	+
45	BRAKE PIPE ASSY <i>new</i>		144.10	+
46	AIR CON BLOWER <i>Cracked</i>		1666.20	✓

47	AIR CON COOLING COIL	Could	1433.10	✓
48	DASHBOARD	Could	1689.90	✓
49	DASHBOARD REINFORCEMENT	Best	873.90	✓
50	DASHBOARD CONSOLE (BLACK)	} Not Nec	298.40	+
51	DASHBOARD COMPARTMENT		384.10	+
52	DASHBOARD GLOVE BOX		521.60	+
53	DASHBOARD GLOVE BOX GARNISH	Not nec	279.40	+
54	SPEEDOMETER	Could	1578.40	✓
55	FLOOR PANEL	Repair	998.70	+
56	FLOOR PANEL MAT	New	541.60	+
57	FRONT DOOR @1474.50	Distorted	2949.00	✓
58	FRONT DOOR LOCK @280.40	Jammed	560.80	✓
59	FRONT DOOR WEATHERSTRIPE @192.70	lt	385.40	✓
60	FRONT DOOR INNER TRIM BOARD @755.90	Could	1511.80	✓
61	FRONT DOOR GLASS @442.90	LH cut, RH shattered	885.80	✓
62	FRONT DOOR GLASS OUTER MOULDING @106.30	LH cut, RH Dehd	212.60	✓
63	FRONT DOOR GLASS REGULATOR MOTOR @368.20	New	736.40	+
64	FRONT DOOR GLASS REGULATOR GEAR @185.10	Dmgd	370.20	✓
65	FRONT DOOR PILLAR @1083.40	Repair	2166.80	x.
66	FRONT WHEEL ARC PANEL @649.40	RH Buckhd	1298.80	699.40
67	FRONT WHEEL ARC GARNISH @145.40	RH Dehd	290.80	145.40
68	FRONT STEP PANEL @385.10	RH Distort	770.20	385.10
69	FRONT STEP PANEL GARNISH @245.20	RH Buckhd	490.40	245.20
70	FUEL TANK	Dented	1225.70	✓
71	FRONT LOWER ARM @320.50	Best	641.00	✓
72	FRONT SHOCK ABSORBER @271.60	Best	543.20	✓
73	FRONT KNUCKLE ARM @857.80	Best	1715.60	✓
74	FRONT WHEEL HUB C/W BEARING @332.80	2nd	665.60	✓
75	STEERING CROSSMEMBER	New	1168.70	+
76	STEERING BOX	Could	686.10	✓

3660520

32944.68

less	10%	53941.10	10%	
		5394.11		
		48546.99		

SPECIAL NETT ITEMS

1	FRONT NUMBER PLATE	Missing	30.00	✓
2	FRONT GRILLE CLIPS	New	20.00	✓
3	ROOF PANEL INNER TRIM CLIPS	New	100.00	+
4	BRAKE FLUID	New	50.00	✓
5	FLOOR PANEL INSULATION PAD	New	280.00	+
6	FRONT WHEEL PANEL PANEL TOP GARNISH CLIPS	M	50.00	20
7	FRONT WHEEL RIM @280	Best	560.00	400
8	FRONT TRYE @200	lt	400.00	300
9	RADIATOR COOLANT	New	50.00	✓

Total Parts 1540.00

870

Vehicle No. GBC597E

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	PANEL BEATING	3500.00	2000
2	SPRAY PAINTING	2500.00	2000
3	WIRING	100.00	50
4	TO APPLY TUFF COAT	300.00	200
5	TO REMOVE FRONT WINDSCREEN	180.00	120
6	TO REMOVE DASHBOARD	350.00	220
7	TO REMOVE CABIN UPHOLSTERY	250.00	120
8	TO REMOVE DRIVER & PASSENGER SEATS	300.00	160
9	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	120.00	60
10	TO REMOVE RADIATOR & TO TOP UP COOLANT	120.00	60
11	TO REMOVE AIR CON SYSTEM	300.00	200
12	TO REMOVE FRONT LH & RH UNDERCARRIAGES	700.00	440
13	TO VACCUM GLASS FRAGMENTS AND TO CLEAN UP INTERIOR	120.00	60
14	TO REPAIR & STRAIGHTEN CHASSIS MEMBERS	800.00	300
15	TO REMOVE BRAKE SYSTEM	250.00	180
16	TO PERFORM WHEEL ALIGNMENT	150.00	80
17	TO LIFT UP CABIN	300.00	280
18	TOWING FEES	120.00 ✓	
	Labour Total :	10460.00	
	TOTAL (PARTS & LABOUR):	60546.59	

6530

Total: 42344.68.

2/s: 22K
(Nett Value)

18 Day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: