

SAM YICK LIAN

1 Kaki Bukit Ave 6,
#01-70 Autobay@Kaki Bukit
Singapore 417883
Tel: 67441373. Fax: 67417138
Reg No: 01939300L

TP Con Pac
Xiao Tony

M/s **Lonpac Insurance Bhd**
101 Thomson Rd
#18-01 United Square
Singapore 307591

Tel: 62507388
Fax: 62962706

ESTIMATE

Date : 14th December 2022
Veh No : **GBD784B**
Make/Model : Nissan NV200
Chassis No : VM20055456
Acc Date : 09/12/2022
Your Ref : XE5275E

S/No.	Qty	Particular	Unit Price	Amount
PARTS				
1	1 pc	Rear Boot Cover <i>Distorted</i>		\$ 2,265.00 <i>1659</i>
2	1 pc	Rear Boot Number Plate Lamp Garnish <i>Delud</i>		\$ 406.60 <i>241</i>
3	1 pc	Rear Boot Centre Logo <i>for race</i>		\$ 74.90 ✓
4	1 pc	Rear Boot Wiper Motor <i>for race</i>		\$ 245.20 ✓
5	1 pc	Rear Boot NV200 Logo <i>over</i>		\$ 108.00 ✓
6	1 pc	Rear Boot Lock <i>Delud</i>		\$ 331.00 <i>278</i>
7	1 pc	Rear Boot Rubber <i>lit</i>		\$ 113.00 ✓
8	2 pcs	Rear Boot Lamp L/R <i>cancel</i>	\$ 291.10	\$ 582.20 ✓
9	2 pcs	Rear Boot Absorber L/R <i>new</i>	\$ 231.10	\$ 462.20 ✓
10	1 pc	Rear End Panel Inner <i>Distorted</i>		\$ 665.00 <i>542</i>
11	1 pc	Rear End Panel Outer		\$ 132.00 ✓
12	1 pc	Rear Boot Inner Garnish <i>Delud</i>		\$ 227.00 ✓
13	1 pc	Rear Bumper <i>Delud</i>		\$ 561.50 ✓
14	2 pcs	Rear Bumper Inner Sponge L/R <i>cancel</i>	\$ 108.00	\$ 216.00 <i>108</i>
15	2 pcs	Rear Boot Hinge L/R <i>new</i>	\$ 42.00	\$ 84.00 ✓
16	1 pc	Rear Boot Glass <i>Delud</i>		\$ 1,523.00 ✓
17	1 pc	Rear End Panel Top Garnish <i>cancel</i>		\$ 285.00 ✓
Total				\$ 8,281.60
Less 10%				\$ 828.16
				\$ 7,453.44

4479.90
less 10%: 4481.91

SPECIAL NETT				
1	1 pc	70km Sticker <i>for</i>		\$ 15.00 ✓
2	1 pc	6 Pax Sticker <i>for</i>		\$ 12.00 ✓
3	1 pc	Windscreen Gum <i>new</i>		\$ 100.00 <i>60</i>
4	1 set	Reverse Sensor <i>new</i>		\$ 200.00 ✓
Total				\$ 327.00

287

LABOUR

1	Labour to change rear windscreen.	\$	160.00	120
2	Labour to provide panel knocking & replace accident parts.	\$	1,800.00	1,000
3	To provide spray painting on accident parts.	\$	1,400.00	800
4	Towing fees.	\$	120.00	
	Labour to remove upholstery 150.80			
	Total	\$	3,480.00	

Total \$ 11,260.44

Labour to remove reverse sensor 100.50

Labour to apply tuff coat 150.60 2110

TS

for SAM YICK LIAN

Adorn G
H/S 15/12/22

07 Days.

total : 6878.91

L/S : 55K

55K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: