



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR22012513/Kwy3m4 Date: 09/02/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 5452R	Veh. Inspected	SLZ 1913E
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/12/22/2029	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	14/12/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA CHR (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	ZYX102099224	Colour	METALLIC BROWN
Odometer	345542 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/50 R18	YOKOHAMA	8 mm
L/H Rear Tyre	225/50 R18	YOKOHAMA	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/12/2022	Inspection Date	14/12/2022
Survey held at	BLK 5038 #01-405 ANG MO KIO IND PK 2 (S 569541)		
Repairer	MASSIVE TRADING & AUTO		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	