



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 1800G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT NUMBER PLATE GARNISH	NOT NECESSARY	78.00	-
1	FRONT BUMPER	DEFORMED	1,526.00	1,526.00
2	FRONT BUMPER SIDE HOLDER @\$98.00	NOT NECESSARY	196.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	685.00	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	165.00	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	255.00	-
4	FRONT BUMPER SENSOR @\$265.00	NOT NECESSARY	1,060.00	-
4	FRONT BUMPER SENSOR HOLDER @\$25.00	NOT NECESSARY	100.00	-
1	FRONT BUMPER LOGO	NECESSARY	72.00	72.00
1	FRONT GRILLE	CRACKED	692.00	692.00
1	FRONT GRILLE LOGO	NOT NECESSARY	75.00	-
1	FRONT GRILLE GARNISH	NOT NECESSARY	265.00	-
2	HEADLAMP @\$2895.00	NOT NECESSARY	5,790.00	-
	LESS 10% DISCOUNT		-1,095.90	-229.00
			9,863.10	2,061.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	30.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET FRONT GRILLE CLIPS (SN)	NOT NECESSARY	20.00	-
			100.00	50.00
<b><u>LABOUR</u></b>				
	PANEL BEATING ,REMOVE AND REFIT PARTS .		400.00	300.00
	SPRAY PAINTING TO AFFECTED AREA .		400.00	250.00
	WIRING CHECK.		50.00	30.00
	TO REMOVE FRONT BUMPER SENSORS .		100.00	50.00
	TO PERFORM DIAGNOSTIC TEST .	NOT NECESSARY	180.00	-
			1,130.00	630.00
<b>GRAND TOTAL</b>			<b>11,093.10</b>	<b>2,741.00</b>

Report Ref No. CS/SMO22012518/Avy3q2



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,200.00</b>
---	--	--	-----------------

Report Ref No. CS/SMO22012518/Avy3q2

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**