

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623 Code: SMO 1. Policy Particulars: - THIRD PARTY CLAIM Insured Veh. EV 1010P Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. CMTD2204574/THE Excess (\$)	MO22012518/Avy3q2 /2023 1800G
SINGAPORE LAND TOWERSINGAPORE 048623 Code: SMO 1. Policy Particulars: - THIRD PARTY CLAIM Insured Veh. EV 1010P Veh. Inspected SMC 1 Policy No. Coverage (\$) 0.00 Claim No. CMTD2204574/THE Excess (\$) 0.00	
1. Policy Particulars :- THIRD PARTY CLAIM Insured Veh. EV 1010P Veh. Inspected SMC 1 Policy No. Coverage (\$) 0.00 Claim No. CMTD2204574/THE Excess (\$) 0.00	1800G
Insured Veh. EV 1010P Veh. Inspected SMC 1	1800G
Policy No. Coverage (\$) 0.00 Claim No. CMTD2204574/THE Excess (\$) 0.00	1800G
Claim No. CMTD2204574/THE Excess (\$) 0.00	
Assign From GRACE TEO Assign Date 14/12/	/2022
2. Vehicle Particulars & Condition	
Make & Model MERCEDES BENZ CLA180 c.c 1595	
Engine No. HIDDEN Year of Reg. 2017	
Chassis No. WDD1173422N441027 Colour BLUE	
Odometer 48616 KM Steering IN OF	RDER
Brakes IN ORDER Modification SPOR	RTS RIM
General GOOD	
3. Conditions of Tyres	
Size Make Balar	nce
R/H Front Tyre 225/40 R18 CONTINENTAL 6 mm	
L/H Front Tyre 225/40 R18 CONTINENTAL 6 mm	
R/H Rear Tyre 225/40 R18 CONTINENTAL 6 mm	
L/H Rear Tyre 225/40 R18 CONTINENTAL 6 mm	
4. Description of Damages	
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.	
DAMAGES SEE DETAILS.	
5. General Information	
Accident Date 12/12/2022 Inspection Date 31/01/	/2023
Survey held at ADVANCE AUTO GARAGE	
23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER, SINGAPORE 415933.	
5a. Remarks	
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	
5b. Estimate Days of Repair	
ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days	