12/20/22, 9:39 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III22010079/SVY3M4-1

20/12/2022 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle GBJ8440J Insured Vehicle No: GBL1932S No:

Date of Loss: 05/02/2022 Nature of Claim: TP Claim No: MFL2022D0005787

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ8440J**

Make & Model: NISSAN NV350, 2.5 PANEL VAN 5AT 5DR (A) YD25055030B **Engine No:**

Reg. Date: 12/09/2019 (Man. Year: 2019) Chassis No: JN1MC2E26Z0031422

Colour: White Odometer: 75637 km

Engine Capacity: 2488 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 195 R15 Rear Tyre Size:

Super Bow Van 5 mm Front Left Side: Super Bow Van 6 mm Rear Left Side: Front Right Side: Super Bow Van 6 mm Rear Right Side: Super Bow Van 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,095.76	1,181.30	1,914.46	61.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	966.00	630.00	336.00	34.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,061.76	1,811.30	2,250.46	55.41
Approved Total (Overridden) (S\$))	1,450.00		
(S\$)	4,061.76	1,450.00	2,611.76	64.30
+ GST 7.00/7.00% (S\$)	284.32	101.50	182.82	64.30
Nett Amount (S\$	4,346.08	1,551.50	2,794.58	64.30

INSPECTION

Date of Assignment: 28/10/2022

GARAGE 13 PTE LTD - KAKI BUKIT (HQ)

8 KAKI BUKIT AVENUE 4, #02-54/55 PREMIER @ Date Inspected: 12/10/2022 Inspected At:

ΚB

SINGAPORE 415875

Estimated Period of Repair: 3.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqubal Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 20 Dec 2022)

Parts: N/A NISSAN NV350 2.5 PANEL VAN 5AT 5DR (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBJ8440J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	921.10 FL	*620.00 FL
2	1		*FRONT BUMPER FOG LAMP COVER RH	Cracked	125.00 FL	*125.00 FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	112.00 FL	*112.00 FL
4	1		*FRONT DOOR STEP GARNISH RH	Not Necessary	144.00 FL	*- FL
5	1		*FRONT CORNER PANEL RH - SLIGHTLY DENTED	Repair	268.00 FL	*- FL
6	2		*HEADLAMP	Cracked	1,667.20 FL	*400.00 FL
7	1		*HEADLAMP PANEL RH - SLIGHTLY DENTED	Not Necessary	146.88 FL	*- FL
8	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
F=Fra	ınchise	part. S=Spcl	Nett. L=ListItemDisc.			
				Sub Total (S\$)	3,434.18	1,307.00
			- List Item Discount on L Ite	ms 10.00/10.00% (S\$)	338.42	125.70
				Total Parts (S\$)	3,095.76	1,181.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	450.00	300.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL	New	450.00	300.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	30.00	0.00
4	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY	New	36.00	30.00
	Gross Labour Cost (S\$)		966.00	630.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >