

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internat	ionale Des Experts Er	n Automo	obile C.S.	3/11122010079
	INDIA INTERNATI	·			10070/Cvy3	
	64 CECIL STREET			Date:	12/10/2022	14/12/2022
				Code:	III2	
	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBL 1932S	Veh. Inspected	d	GBJ 8440J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.		Excess (\$)		0.00	
	Assign From	CARINE KEK	Assign Date		42/10/2022	14/12/2022
1		Vehicle Par	ticulars & Conditi	ion		
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
		Descrip	tion of Damages			
•		Gener	ral Information			
	Accident Date	05/02/2022	Inspection Dat	:e	12/10/2022	
	Survey held at	8 KAKI BUKIT AVE 4 #02-54/5	55 PREMIER @ KB			
	Repairer	GARAGE 13 PTE LTD				
a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					