



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2206753

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 02/11/2022
Reference CS3/III22010079/Svy3m4
Code III2

PROFESSIONAL SERVICE FEE

Bill cancel refer to new invoice No. AC2207799 20/12/2022 \$261.00

Vehicle No. GBJ 8440J

Insured Veh. GBL 1932S

Claim No.

Policy No.

Accident Date 05/02/2022

Inspection Date 12/10/2022

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 12.10.2022 03.40pm	
- Dismantle Inspection 13.10.2022 01.30pm	
- After Repair Inspection 17.10.2022 11.50am	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2207799

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 20/12/2022
Reference CS3/III22010079/Svy3m4-1
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. GBJ 8440J
Insured Veh. GBL 1932S
Claim No. MFL2022D0005787
Policy No. D19MFL0005549_02
Accident Date 05/02/2022
Inspection Date 12/10/2022

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Merimen Fee	11.00
Note: Pls discard Inv.AC2206753 dated 02/11/2022 \$140.17	
Subtotal	261.00
GST (7%)	18.27
Grand Total	279.27

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML