



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2300208

64 CECIL STREET  
#05-02 IOB BUILDING  
SINGAPORE 049711

INV Date 12/01/2023  
Reference CS3/GRB21008500/Tvy3e2-  
'  
Code GRB

### PROFESSIONAL SERVICE FEE

Vehicle No. FBS 929Y  
Insured Veh. SLK 8639E  
Claim No. MFL2021D0003332  
Policy No. D21MFL0000447  
Accident Date 04/08/2021  
Inspection Date 13/08/2021

Description	Total
Survey Inspection	250.00
Digital Photographs	
Transportation	
Less: Pre-Repair Survey Fee (Invoice.AC2105823 dated 18/08/2021)	-120.00
<b>Subtotal</b>	<b>130.00</b>
<b>GST (8%)</b>	<b>10.40</b>
<b>Grand Total</b>	<b>140.40</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**KHM**