



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428		Ref: CS/LIP22012528/Kwy3e2 Date: 22/12/2022 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SCU 7883B	Veh. Inspected	SJR 3904J
Policy No.		Coverage (\$)	0.00
Claim No.	IVS22/2148	Excess (\$)	0.00
Assign From	ANDY SEAH	Assign Date	15/12/2022
2. Vehicle Particulars & Condition			
Make & Model	SUZUKI SX4 (A)	c.c	1586
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	JSAGYC21S00203781	Colour	METALLIC SILVER
Odometer	225569 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	DELIUM	8 mm
L/H Front Tyre	195/65 R15	DELIUM	8 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/12/2022	Inspection Date	15/12/2022
Survey held at	TSR AUTOMOTIVE PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)REGISTRATION DATE: 23 JUN 2009 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	