

SPEEDWERKZ PRIVATE LIMITED

1 Kaki Bukit Ave 6 #01-73, AUTOBAY Singapore 417883

Tel: 96195936 / info@speedwerkz.biz

TP SMRT.

Veron

VEHICLE NUMBER: JQA3078

MAKE & MODEL: HONDA CIVIC 2.0

DOA: 15/10/2022

CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
FRONT BUMPER <i>Distorted</i>	1	\$1,231.00	<i>685</i>
FRONT GRILLE TOP <i>new</i>	1	\$395.50	<i>x</i>
FRONT BUMPER LOWER GRILLE TRIM <i>new</i>	1	\$267.50	<i>+</i>
FRONT BUMPER LOWER GRILLE	1	\$214.50	<i>+</i>
FRONT BUMPER REINFORMENT <i>new</i>	1	\$589.50	<i>+</i>
FRONT BUMPER SIDE RETAINER @65 <i>new</i>	2	\$130.00	<i>70</i>
FRONT BUMPER TOP BEAM <i>new</i>	1	\$314.80	<i>x</i>
FRONT BUMPER PLATE GARNISH <i>new</i>	1	\$89.00	<i>x</i>
FRONT BUMPER FOG LAMP	2	\$452.00	<i>+</i>
FRONT BUMPER FOG LAMP COVER @115.00 <i>new</i>	2	\$230.00	<i>+</i>
FRONT BONNET <i>new</i>	1	\$1,252.00	<i>+</i>
FRONT BONNET INSULATOR	1	\$351.00	<i>+</i>
FRONT BONNET LOCK	1	\$265.50	<i>+</i>
FRONT BONNET HINGE @76.00	2	\$152.00	<i>+</i>
FRONT SUPPORT PANEL	1	\$956.50	<i>x</i>
FRONT SUPPORT PANEL TOP GARNISH <i>new</i>	1	\$312.20	<i>+</i>
FRONT HEAD LAMP @1365 <i>LH cut</i>	2	\$2,730.00	<i>780</i>
FRONT HEAD LAMP PANEL <i>new</i>	1	\$135.00	<i>x</i>
FRONT HEAD LAMP LOWER BEAM @101	2	\$202.00	<i>x</i>
FRONT FENDER @ 785 <i>LH Distorted</i>	2	\$1,570.00	<i>785</i>
FRONT FENDER COWLING @195.00 <i>LH Distorted</i>	2	\$390.00	<i>195</i>
FRONT FENDER INNER PANEL @855.00 <i>new</i>	2	\$1,710.00	<i>+</i>
SIDE SKIRT RH <i>new</i>	1	\$600.00	<i>+</i>
FRONT DOOR @ 1365.20 LH <i>Distorted</i>	1	\$1,365.20	<i>1150</i>
FRONT DOOR GLASS OUTER MOULDING @215.20 LH <i>new</i>	1	\$215.20	<i>+</i>
FRONT DOOR GLASS RUN CHANNEL @395.60 LH <i>new</i>	1	\$395.60	<i>+</i>
FRONT DOOR GLASS REGULATOR @478.10	1	\$478.10	<i>+</i>
FRONT DOOR GLASS REGULATOR MOTOR @ 395.60 LH <i>new</i>	1	\$395.60	<i>x</i>
FRONT DOOR SIDE MIRROR @798.50 LH <i>new</i>	1	\$198.50	<i>+</i>
FRONT DOOR OUTER HANDLE @165.90 LH <i>new</i>	1	\$165.90	<i>+</i>
FRONT DOOR INNER BOARD @994.20 LH <i>new</i>	1	\$994.20	<i>+</i>
FRONT DOOR LOCK @396.60 LH	1	\$396.60	<i>x</i>
FRONT DOOR HINGE @85 LH	1	\$85.00	<i>+</i>
FRONT DOOR CHECK @89.50 LH	1	\$89.50	<i>+</i>
FRONT DOOR WEATHERSHIP INNER @395.20 LH <i>new</i>	1	\$395.20	<i>x</i>
FRONT DOOR WEATHERSHIP OUTER @314.10 LH	1	\$314.10	<i>+</i>
FRONT DOOR BLACK TAPE @95.20 LH <i>new</i>	1	\$95.20	<i>+</i>

FRONT SHOCK ABSORBER @581.20 <i>Best</i>	2	\$1,162.40	<i>200</i>
FRONT SHOCK ABSORBER MOUNTING @189.20 <i>new</i>	2	\$378.40	<i>+</i>
FRONT SHOCK ABSORBER DUMPER @35 <i>new</i>	2	\$70.00	<i>x</i>
FRONT KNUCKLE ARM @639.50 <i>new</i>	2	\$1,279.00	<i>880</i>
FRONT WHEEL BEARING @365.20 <i>new</i>	2	\$730.40	<i>580</i>
FRONT WHEEL BEARING HUB @ 361.40 <i>new</i>	2	\$722.80	<i>500</i>
FRONT STABILIZER BAR LINK <i>new</i>	1	\$123.00	<i>+</i>
FRONT LOWER ARM @541.20 <i>Best</i>	2	\$1,082.40	<i>785</i>
FRONT TRAIL ARM @685 <i>new</i>	2	\$1,370.00	<i>+</i>
FRONT WHEEL BEARING WITH HUB <i>new</i>	1	\$322.00	<i>x</i>
DRIVER SEAT MECHANISM <i>new</i>	1	\$688.00	<i>x</i>

7413.70

5930.96

Less 10 % \$28,052.30
Sub Total \$5,610.46
\$22,441.84

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
FRONT NUMBER PLATE <i>new</i>	1	\$45.00	<i>+</i>
FRONT SPORT RIM <i>new</i>	1 SET	\$2,500.00	<i>1000</i>
FRONT TYRE <i>new</i>	1 SET	\$1,500.00	<i>x</i>
FRONT FENDER INNER SHIELD CLIPS <i>new</i>	1 SET	\$50.00	<i>30</i>
FRONT BUMPER CLIPS	1 SET	\$50.00	<i>30</i>

1060

Sub Total \$4,145.00

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
TO CHECK WIRING		\$200.00	<i>30</i>
TUFF KOTE		\$200.00	<i>60</i>
REMOVE AND REFIX CUSHION SEAT CARPET , UPHOLSTERY ETC		\$200.00	<i>80</i>
REMOVE AND REFIX FRONT UNDER CARRIAGE , SUSPENSION ETC		\$1,200.00	<i>440</i>
CHECK WHEEL ALIGNMENT		\$120.00	<i>80</i>
REMOVE SPARE PARTS AND PANEL BEATING		\$2,500.00	<i>1000</i>
RESPRAY PAINTING		\$2,500.00	<i>1200</i>

2890

Sub Total \$6,920.00

Grand Total \$33,506.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin LG

2/s 15/12/22

10 Days

total: 9880.96

1/s: 7.9K

CITY TYREAUTO PTE LTD
219 KAKI BUKIT AVE 1
SHUN LI INDUSTRIAL PARK
SINGAPORE 416044
TEL: 67466686
H/P: 85153676

Work Order: R005643
 License: JQA3078
 Date: 15.12.22 13:26

Honda : Civic : 2012-16 (FB/FG) : except 18" Wheel : Type B

Front : Left

Actual	Before	Specified Range
2°08'	2°08'	-0°10' 0°50'
5°10'	5°10'	4°40' 5°40'
0°51'	0°51'	-0°05' 0°05'
-1°38'	-1°38'	
0°30'	0°30'	

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
1°47'	1°47'	-0°10' 0°50'
5°10'	5°10'	4°40' 5°40'
0°38'	0°38'	-0°05' 0°05'
-1°17'	-1°17'	
0°30'	0°30'	

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°21'	0°21'	-0°45' 0°45'
0°00'	0°00'	
-0°21'	-0°21'	
1°29'	1°29'	-0°09' 0°09'

Rear : Left

Actual	Before	Specified Range
-1°04'	-1°04'	-1°07' 0°23'
0°20'	0°20'	0°02' 0°09'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°04'	-1°04'	-1°07' 0°23'
0°00'	0°00'	0°02' 0°09'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°00'	0°00'	-0°45' 0°45'
0°20'	0°20'	0°05' 0°19'
0°10'	0°10'	