



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SNE1148J  
Date of Accident : 14 December 2022

Mr Teo Han Boon

Date : 15 December 2022

Estimate To Repair SMP8772P - Toyota PRIUS PLUS (AUTO)

Chassis No : JTDZS3EU70J051701

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	n/s rear door	\$ Ry 1,401.70
02	1 pc	n/s rear door moulding	\$ nm x 99.90
03	1 pc	n/s rear door weatherstrip	\$ nm x 193.90
04	1 pc	n/s rear fender	\$ pt 1,045.40
05	1 pc	n/s rear fender inner cowling	\$ nm x 157.90
06	1 pc	n/s rear fender sticker	\$ net 24.90
07	1 pc	n/s rear petrol tank door cover	\$ nm x 98.00
08	1 pc	rear bumper	\$ de 602.60
09	8 ps	rear bumper clips @ \$4.50	\$ net 36.00
10	1 pc	n/s rear bumper bracket	\$ nm x 154.20
11	1 pc	n/s rear wheel cap	\$ ent 85.00
Less 25 %			\$ 1793.90 \$ 1345.42
<u>SPECIAL NETT ITEMS</u>			
12	1 pc	n/s rear fender quarter glass prime	\$ net 50.00
13	1 tube	n/s rear fender quarter glass sealant	\$ net 60.00
14	1 pc	n/s rear tyre	\$ XM 300.00
			\$ 110 \$ 410.00
<u>LABOUR &amp; MISC. CHARGES</u>			
01		To transfer of n/s rear door fittings and perform water seepage test.	\$ nm x 80.00
02		To drop petrol tank, hoses to facilitate bodywork repair, final checking and testing.	\$ 0.00
03		To rust-proofing of the affected areas.	\$ 30 100.00
04		Putty and spray painting of the affected portion.	\$ 600 900.00
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 600 850.00
			\$ 1,930.00
Total			\$ 5,264.63
<p>Tan Lim 97495749 WP 15/12/22 @ 1130 LB Resurvey after repair Tan Lim @ Khantowm 5 days To remove and refit quarter glass</p>			<p>1310 1345.42 110 1310 2765.42 43\$2200 80 : \$200.00</p>