

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	SU220149
Policy No:	SP2000756192-01	Date of Loss:	11/12/2022
Vehicle Reg. No.:	SLR8450U	Driveable?	
Driver Age/Info:	29 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	Runjeet Singh S/O Mukhtar Singh	Contact No:	+6594509447
Driver:	Goi Kai Bei		
Make/Model:	NISSAN SYLPHY, 1.5 4AT ABS D/AB 2WD 4DR (A)	Vehicle Reg. Date:	08/01/2010
Vehicle Colour:	White		
Engine No:	HR15285304B	Chassis No:	JN1BAAG11Z0110642
Odometer:	180089 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	SUCCESS UNITED PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	2,834.20
Miscellaneous Items	0.00
Labour	880.00
Paintwork Labour	900.00
Towing	0.00
Calculated Gross Total (S\$)	4,614.20
- Excess (S\$)	500.00
(S\$)	4,114.20
+ GST 7.00% (S\$)	287.99
Nett Amount (S\$)	4,402.19

This claim is handled by: **LAW YI TING**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Dec 2022)

Parts: 143 NISSAN SYLPHY 1.5 4AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Success United Pte Ltd/SLR8450U/14/12/2022 16:15

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER ASSY	0.00	0.00	*350.00 F
2	1		*FRT BUMPER CLIPS	0	0.00	*30.00 FS
3	2		*FRT BUMPER SIDE HOLDER L/RH	0.00	0.00	*60.00 F
4	1		*FRT BUMPER BRACKET LH	0.00	0.00	*85.00 F
5	1		*FRT BUMPER CHROME TRIM	0.00	0.00	*35.00 F
6	1		*FRT BUMPER FOGLAMP COVER LH	0.00	0.00	*42.00 F
7	1		*FRT BUMPER FOGLAMP ASSY LH	0.00	0.00	*180.00 F
8	1		*FRT BUMPER LOWER AIR GRILLE	0.00	0.00	*70.00 F
9	1		*FRT BUMPER INNER SPONGE	0.00	0.00	*150.00 F
10	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	*200.00 F
11	1		*FRT HEADLAMP ASSY LH	0.00	0.00	*325.00 F
12	1		*FRT GRILLE ASSY	0.00	0.00	*165.00 F
13	1		*FRT BONNET	0.00	0.00	*490.00 F
14	1		*FRT BONNET MECHANISM LOCK	0.00	0.00	*70.00 F
15	1		*RADIATOR SUPPORT PANEL ASSY	0.00	0.00	*180.00 F
16	1		*RADIATOR SUPPORT PANEL TOP LOWER GARNISH	0.00	0.00	*120.00 F
17	1		*RADIATOR SUPPORT PANEL TOP LOWER GARNISH CLIPS	0	0.00	*30.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	2,582.00
+ Margin on L,N Items 10.00% (\$\$)	252.20
Total Parts (\$\$)	2,834.20

Success United Pte Ltd/SLR8450U/14/12/2022 16:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	To putty and respray painting on bonnet, bumper, fender LH and support panel	New	900.00
Labour Items			
2	To remove, repair and replaced damaged bodyparts, realigned bodyworks & where consistent to the accident	New	800.00
3	To remove, rearrange electrical wiring,check lighting	New	80.00
Gross Labour Cost (S\$)			1,780.00

Success United Pte Ltd/SLR8450U/14/12/2022 16:15. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >