

Success United Pte Ltd (Co.Reg.No:200402570G)

2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub

Singapore 417921

Tel: 6746 1515 Fax: 6748 5015 Email: sirina@successunited.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	SU220149
Policy No:	SP2000756192-01	Date of Loss:	11/12/2022
Vehicle Reg. No.:	SLR8450U	Driveable?	
Driver Age/Info:	29 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	RUNJEET SINGH S/O MUKHTAR SINGH	Contact No:	+6594509447
Driver:	GOI KAI BEI		

Make/Model:	NISSAN SYLPHY, 1.5 4AT ABS D/AB 2WD 4DR (A)	Vehicle Reg. Date:	08/01/2010
Vehicle Colour:	WHITE		
Engine No:	HR15285304B	Chassis No:	JN1BAAG11Z0110642
Odometer:	180089 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		

Description of Accident/Loss	REFER TO SKETCH PLAN.
Present Location:	SUCCESS UNITED PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	2,834.20
Miscellaneous Items	0.00
Labour	880.00
Paintwork Labour	900.00
Towing	0.00
Calculated Gross Total (S\$)	4,614.20
- Excess (S\$)	500.00
(S\$)	4,114.20
+ GST 7.00% (S\$)	287.99
Nett Amount (S\$)	4,402.19

This claim is handled by: LAW YI TING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 14 Dec 2022)**Parts:** 143 NISSAN SYLPHY 1.5 4AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Success United Pte Ltd/SLR8450U/14/12/2022 16:15**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER ASSY	0.00	0.00	*350.00 F DD
2	1		*FRT BUMPER CLIPS	0	0.00	*30.00 FS NEC
3	2		*FRT BUMPER SIDE HOLDER L/RH LH-CRA, RH- RA	0.00	0.00	*60.00 F
4	1		*FRT BUMPER BRACKET LH	0.00	0.00	*85.00 F
5	1		*FRT BUMPER CHROME TRIM	0.00	0.00	*35.00 F CUT
6	1		*FRT BUMPER FOGLAMP COVER LH	0.00	0.00	*42.00 F
7	1		*FRT BUMPER FOGLAMP ASSY LH	0.00	0.00	*180.00 F
8	1		*FRT BUMPER LOWER AIR GRILLE	0.00	0.00	*70.00 F
9	1		*FRT BUMPER INNER SPONGE	0.00	0.00	*150.00 F
10	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	*200.00 F
11	1		*FRT HEADLAMP ASSY LH CRA	0.00	0.00	*325.00 F
12	1		*FRT GRILLE ASSY	0.00	0.00	*165.00 F
13	1		*FRT BONNET	0.00	0.00	*490.00 F
14	1		*FRT BONNET MECHANISM LOCK	0.00	0.00	*70.00 F
15	1		*RADIATOR SUPPORT PANEL ASSY	0.00	0.00	*180.00 F
16	1		*RADIATOR SUPPORT PANEL TOP LOWER GARNISH	0.00	0.00	*120.00 F
17	1		*RADIATOR SUPPORT PANEL TOP LOWER GARNISH CLIPS	0	0.00	*30.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	2,582.00
+ Margin on L,N Items 10.00% (\$\$)	252.20
Total Parts (\$\$)	2,834.20

Success United Pte Ltd/SLR8450U/14/12/2022 16:15. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To putty and respray painting on bonnet, bumper, fender LH and support panel	New	900.00 600
<u>Labour Items</u>			
2	To remove, repair and replaced damaged bodyparts, realigned bodyworks & where consistent to the accident	New	800.00 500
3	To remove, rearrange electrical wiring, check lighting	New	80.00 30
Gross Labour Cost (S\$)			1,780.00

Success United Pte Ltd/SLR8450U/14/12/2022 16:15. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

p/s or L/S?

5 days to repair.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: