

(08/11/13) wef

ASS. REC. BY: /

REF:

CS6/A1820012540/Cvy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. SP2000756192-01

Claims No. 202222008810

Sum Insured: _____ Excess: 500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$23K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 2026 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLR 84504 Yr Regn: Jan/ 2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Sylphy 1.5L c.c. 1498

Colour: white A/C: Insured / Std / NI / NA

Sp.Reading: 180089 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: IN1BAAG112 * 0110642

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 / 65 R15

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fireza

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. 4 mm L/Bal. 4 mm

D.O.A. 11/12/22 D.O.I. 14/12/22

Survey held at Desktop

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/12/22 Lump Sum \$2250 confirmed by email (Red 2364.20 ,51%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 27/12/22-typist

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

____ S + RS, ____ SI

Photos

Others

TOTAL

Report Format : Merimen

Lump Sum / I.B.I. (\$ 2250)

> Back to OneMotoring

D.O.A. : 11/12/2022
Bal. : 2 yrs 0.7mth.
M.V. \$23,000.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	964B
Vehicle Details	
Vehicle No.:	SLR8450U
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Dec 2022
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.5L 4AT ABS D/AB 2WD 4DR
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	HR15285304B
Chassis No.:	JN1BAAG11Z0110642
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$18,111.00
Original Registration Date:	08 Jan 2010
First Registration Date:	08 Jan 2010
Transfer Count:	4
Actual ARF Paid:	\$18,111.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$15,988.00
COE Rebate Amount:	\$6,558.00
Total Rebate Amount:	\$6,558.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 12 Dec 2022

OK

N.V. \$16,000.

Success United Pte Ltd (Co.Reg.No:200402570G)

2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub

Singapore 417921

Tel: 6746 1515 Fax: 6748 5015 Email: sirina@successunited.com.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	SU220149
Policy No:	SP2000756192-01	Date of Loss:	11/12/2022
Vehicle Reg. No.:	SLR8450U	Driveable?	
Driver Age/Info:	29 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	RUNJEET SINGH S/O MUKHTAR SINGH	Contact No:	+6594509447
Driver:	GOI KAI BEI		

Make/Model:	NISSAN SYLPHY, 1.5 4AT ABS D/AB 2WD 4DR (A)	Vehicle Reg. Date:	08/01/2010
Vehicle Colour:	WHITE		
Engine No:	HR15285304B	Chassis No:	JN1BAAG11Z0110642
Odometer:	180089 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		

Description of Accident/Loss	REFER TO SKETCH PLAN.
Present Location:	SUCCESS UNITED PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	2,834.20
Miscellaneous Items	0.00
Labour	880.00
Paintwork Labour	900.00
Towing	0.00
Calculated Gross Total (S\$)	4,614.20
- Excess (S\$)	500.00
(S\$)	4,114.20
+ GST 7.00% (S\$)	287.99
Nett Amount (S\$)	4,402.19

This claim is handled by: LAW YI TING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 14 Dec 2022)**Parts:** 143 NISSAN SYLPHY 1.5 4AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Success United Pte Ltd/SLR8450U/14/12/2022 16:15**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER ASSY	0.00	0.00	*350.00 F DD
2	1		*FRT BUMPER CLIPS	0	0.00	*30.00 FS NEC
3	2		*FRT BUMPER SIDE HOLDER L/RH LH-CRA, RH- 7	0.00	0.00	*60.00 F VOA
4	1		*FRT BUMPER BRACKET LH	0.00	0.00	*85.00 F VOA
5	1		*FRT BUMPER CHROME TRIM	0.00	0.00	*35.00 F CUT
6	1		*FRT BUMPER FOGLAMP COVER LH	0.00	0.00	*42.00 F R/CRA
7	1		*FRT BUMPER FOGLAMP ASSY LH	0.00	0.00	*180.00 F R/CRA
8	1		*FRT BUMPER LOWER AIR GRILLE	0.00	0.00	*70.00 F XNN
9	1		*FRT BUMPER INNER SPONGE	0.00	0.00	*150.00 F CRA
10	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	*200.00 F XNN
11	1		*FRT HEADLAMP ASSY LH CRA	0.00	0.00	*325.00 F CUT
12	1		*FRT GRILLE ASSY	0.00	0.00	*165.00 F VOA
13	1		*FRT BONNET	0.00	0.00	*490.00 F X R
14	1		*FRT BONNET MECHANISM LOCK	0.00	0.00	*70.00 F X SVC
15	1		*RADIATOR SUPPORT PANEL ASSY	0.00	0.00	*180.00 F PR
16	1		*RADIATOR SUPPORT PANEL TOP LOWER GARNISH	0.00	0.00	*120.00 F DIS
17	1		*RADIATOR SUPPORT PANEL TOP LOWER GARNISH CLIPS	0	0.00	*30.00 FS NEC

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	2,582.00
+ Margin on L,N Items 10.00% (\$\$)	252.20
Total Parts (\$\$)	2,834.20

Success United Pte Ltd/SLR8450U/14/12/2022 16:15. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	To putty and respray painting on bonnet, bumper, fender LH and support panel	New	900.00 600
Labour Items			
2	To remove, repair and replaced damaged bodyparts, realigned bodyworks & where consistent to the accident	New	800.00 500
3	To remove, rearrange electrical wiring, check lighting	New	80.00 30
Gross Labour Cost (S\$)			1,780.00

Success United Pte Ltd/SLR8450U/14/12/2022 16:15. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

P/S or L/S?

5 days to repair.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: