

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CC3/AIG22012546/AVP3M4  
**Date:** 03/04/2023**REFERENCE**

Insured/Claimant:	STEPHEN MCNULTY	Policy No:	7220055041		
Date of Loss:	09/12/2022	Nature of Claim:	OD	Claim No:	3414782113SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SNF3268C</b>		Engine No:	DEM034525
Make & Model:	AUDI A5 SPORTBACK, 2.0 TFSI S TRONIC (110 KW) (A)		Chassis No:	WAUZZZF55MA062382
Reg. Date:	20/05/2022 (Man. Year: 2021)		Odometer:	10245 km
Colour:	White			
Engine Capacity:	1984 cc			
Market Value/New Car Price:	S\$245,000.00			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,348.00	0.00	6,348.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,152.00	2,402.00	1,750.00	42.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,500.00</b>	<b>2,402.00</b>	<b>8,098.00</b>	<b>77.12</b>
<b>- Excess (S\$)</b>	1,600.00	1,600.00	0.00	0.00
<b>(S\$)</b>	8,900.00	802.00	8,098.00	90.99
<b>+ GST 8.00/8.00% (S\$)</b>	712.00	64.16	647.84	90.99
<b>Nett Amount (S\$)</b>	<b>9,612.00</b>	<b>866.16</b>	<b>8,745.84</b>	<b>90.99</b>

**INSPECTION**

Date of Assignment:	15/12/2022		
Date Inspected:	14/12/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,609.00 FS	*- FS
2	1		*REAR BUMPER SECURING STRIP - LOWER	Not Necessary	125.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP - UPPER	Not Necessary	249.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	276.00 FS	*- FS
5	1		*REAR BUMPER BRACKET - RH	Not Necessary	228.00 FS	*- FS
6	2		*REAR BUMPER REFLECTOR - LH / RH	Not Necessary	96.00 FS	*- FS
7	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,131.00 FS	*- FS
8	2		*REAR BUMPER IMPACT BAR GASKET - LH / RH	Not Necessary	32.00 FS	*- FS
9	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	49.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION - RH UPPER	Not Necessary	26.00 FS	*- FS
11	1		*REAR BUMPER HOLDING STRAP - RH	Not Necessary	94.00 FS	*- FS
12	1		*REAR PARKING AID SENSOR - OUTER	Not Necessary	266.00 FS	*- FS
13	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
14	1		*EXHAUST TAIL PIPE TRIM - RH	Not Necessary	383.00 FS	*- FS
15	1		*REAR VENT TRIM	Not Necessary	75.00 FS	*- FS
16	1		*REAR WHEEL HOUSING LINER - RH	Not Necessary	299.00 FS	*- FS
17	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>6,348.00</b>	<b>0.00</b>
---------------------------	-----------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	750.00
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER	New	2,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>4,152.00</b>	<b>2,402.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >