

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1114/2022/EQ
DATE : 13-Dec-22
WIP : 54570

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/12/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR STEPHEN MCNULTY
ADDRESS : 55 COVE DRIVE
#05-09
SINGAPORE 098395
TELEPHONE : HP +65 91054013
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220055041
VEHICLE NO : **SNF 3268 C**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 20/5/2022
ENGINE NO : DEM 034525
CHASSIS NO : WAUZZZF55MA062382
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 9-Dec-22
PLACE OF ACCIDENT : ECP WESTBOUND NEAR STILL ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNF 3268 C

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00	750
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER.	\$	2,000.00	1100
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 4,152.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 3268 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Repis</i>	1	\$ 2,609.00	<i>f</i>
2	REAR BUMPER SECURING STRIP - LOWER	1	\$ 125.00	<i>f</i>
3	REAR BUMPER SECURING STRIP - UPPER	1	\$ 249.00	<i>f</i>
4	REAR BUMPER SPOILER	1	\$ 276.00	<i>f</i>
5	REAR BUMPER BRACKET - RH	1	\$ 228.00	<i>f</i>
6	REAR BUMPER REFLECTOR - LH / RH	2	\$ 96.00	<i>f</i>
7	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,131.00	<i>f</i>
8	REAR BUMPER IMPACT BAR GASKET - LH / RH	2	\$ 32.00	<i>f</i>
9	REAR BUMPER GUIDE SECTION - RH	1	\$ 49.00	<i>f</i>
10	REAR BUMPER GUIDE SECTION - RH UPPER	1	\$ 26.00	<i>f</i>
11	REAR BUMPER HOLDING STRAP - RH	1	\$ 94.00	<i>f</i>
12	REAR PARKING AID SENSOR - OUTER	1	\$ 266.00	<i>f</i>
13	REAR PARKING AID SEAL RING	4	\$ 10.00	<i>f</i>
14	EXHAUST TAIL PIPE TRIM - RH	1	\$ 383.00	<i>f</i>
15	REAR VENT TRIM	1	\$ 75.00	<i>f</i>
16	REAR WHEEL HOUSING LINER - RH	1	\$ 299.00	<i>f</i>
17	SUNDRIES <i>nn</i>		\$ 400.00	<i>f</i> X
TOTAL SPARE PARTS			\$ 6,348.00	
TOTAL LABOUR CHARGES			\$ 4,152.00	
GRAND TOTAL			\$ 10,500.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ly*
SURVEYED DATE : *14/12/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT