



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C



FROM : Jaclyn Lai
TEL. NO. : 6265-0026 / 9236-8218
EMAIL : jaclynlai@asmauto.com.sg
TO : Allianz Insurance Singapore Pte. Ltd.
ATTN : Motor Claim Department
TEL. NO. : 6714 3369
EMAIL : claims@allianz.com.sg
CC : Access Systems Technology Pte Ltd

DATE : 15.12.2022
VEHICLE NO. : GBL 4566 X
MODEL NO. : TOYOTA DYNA 150 5MT
CHASSIS NO. : JTFAT35YX0K216686
ENGINE NO. : 1KDB091088 (2982 cc)
LTA REG DATE : 26.07.2021 - 25.07.2031
CLAIM TYPE : Third Party - GBJ 6673 S
D.O.A : 25.11.2022
CLAIM REF NO. : asm/AC22125/JL

QUOTATION FOR ACCIDENT REPAIR

<u>S/N</u>	<u>SPARE PARTS</u>	<u>QTY</u>	<u>UOM</u>	<u>UNIT PRICE</u>	<u>AMOUNT</u>
1	Mirror stay, LH	1	pc	\$ 978.10	\$ 978.10
2	Front panel	1	pc	\$ 1,718.10	\$ 1,718.10
3	Radiator grille	1	pc	\$ 978.10	\$ 978.10
4	Headlamp assy, RH	1	unit	\$ 1,819.10	\$ 1,819.10
5	Front bumper	1	pc	\$ 570.10	\$ 570.10
SUB-TOTAL :					\$ 6,063.50
LESS 25% :					\$ 1,515.88
TOTAL :					\$ 4,547.63

<u>S/N</u>	<u>SPARE PARTS (SPECIAL NETT ITEMS)</u>	<u>QTY</u>	<u>UOM</u>	<u>UNIT PRICE</u>	<u>AMOUNT</u>
1	Radiator grille clips	10	pcs	\$ 8.00	\$ 80.00
S/N ITEMS TOTAL :					\$ 80.00
TOTAL PARTS :					\$ 4,627.63

<u>S/N</u>	<u>LABOUR CHARGES</u>	<u>AMOUNT</u>
1	Remove front windscreen, windshield panel, instrument panel and other attached parts, to cut and remove front panel, replace and welding new panel. Remove and replace other headlamp, radiator grille, bumper etc. Reinstall necessary parts after repaired. (\$250 x 8 days)	\$ 2,000.00
2	Spray painting	\$ 750.00
TOTAL LABOUR :		\$ 2,750.00
GRAND TOTAL :		\$ 7,377.63