

COMFORT TRANSPORTATION PTE LTD
REPAIR ESTIMATE

Vehicle No. : SHC2651Y

Make : HYUNDAI

Model : IONIQ (G2)

Date: 14/12/2022

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$ 459.40
10	REAR BUMPER CLIPS			\$ 22.00
1	REAR BUMPER SIDE BRACKET RH			\$ 55.80
1	REAR WHEEL RIM RH			\$ 1,124.20
	SUB TOTAL			\$ 1,661.40
	LESS 20%			\$ 332.28
	DISCOUNTED TOTAL			\$ 1,329.12
	REAR BUMPER RUBBER MAT			\$ 50.00
			NETT	\$ 50.00
	Labour Charge			
	PANEL BEATING			\$ 1,050.00
	SPRAY PAINTING CHARGE			\$ 600.00
	REMOVE/ REFIX REVERSE SENSOR			\$ 60.00
	TOTAL LABOUR			\$ 1,710.00
	ESTIMATE TOTAL			\$ 3,089.12

✓ DEF
 ✓ NEC
 ? XSVL
 X SVC

✓ NEC

\$ 700
 500
 300

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKK

14/12/2022 1600

LIS

3 days

CHECK ITEM PHOTOS

PHOTO REPAIR PHOTOS kindly take note DOA. 22.07-22

accident take place.

LKK Auto Centre is hereby notified

- the Repair estimate is for your information
- To resurvey the vehicle and provide a final estimate
- To display the estimate and parts list to you
- Parts prices are subject to change
- Third party survey is on a "no liability" basis
- No illegal or unlicensed work will be carried out
- Supplier of parts and labour is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: