

The Motor Claims Department
M/s Lonpac Insurance Bhd
100 Beach Road
#19-00 Shaw Tower
Singapore 189702

File No : SH/2022/330/12/014/OD
Date : 15-December-2022

Estimated cost of repair for vehicle no : SKX1568R Audi A3
Policy no: Z22VP05032269 Accident Date: 10.12.2022

Description	Quantity	Cost Price
Bonnet	1	\$ 1,200.00
RH Bonnet hinge	1	\$ 40.00
LH Bonnet hinge	1	\$ 40.00
RH bonnet lock	1	\$ 90.00
LH bonnet lock	1	\$ 90.00
Bonnet front rubber seal	1	\$ 18.00
RH head lamp	1	\$ 1,350.00
LH head lamp	1	\$ 1,350.00
LH front fender	1	\$ 400.00
LH front fender wheel cowling	1	\$ 90.00
LH front fender wheel cowling clips (1 set)	1	\$ 15.00
Front grille	1	\$ 380.00
Front grille inner panel	1	\$ 30.00
Front bumper	1	\$ 850.00
Front bumper sponge	1	\$ 50.00
Front bumper reinforcement	1	\$ 380.00
Front bumper tow cover	1	\$ 30.00
RH Front bumper fog lamp cover with chrome	1	\$ 70.00
LH Front bumper fog lamp cover with chrome	1	\$ 70.00
Front bumper bottom dust cover	1	\$ 160.00
RH Front bumper retainer	1	\$ 45.00
LH Front bumper retainer	1	\$ 45.00
RH Front bumper bracket	1	\$ 70.00
LH Front bumper bracket	1	\$ 70.00
LH Front bumper headlamp washer jet	1	\$ 110.00
LH Front bumper headlamp washer jet cover	1	\$ 30.00
Front support panel	1	\$ 400.00
Front support panel top air duct	1	\$ 45.00
Front support panel top air duct upper cover	1	\$ 30.00
Air con condensor	1	\$ 450.00
RH Air con condensor air guide	1	\$ 20.00
LH Air con condensor air guide	1	\$ 20.00
Radiator	1	\$ 450.00
Radiator auto fan	1	\$ 650.00
Radiator auto fan cowling	1	\$ 160.00
Auxiliary Radiator	1	\$ 350.00

Horn	1	\$	90.00
Wiper water tank	1	\$	110.00
Steering wheel air bag	1	\$	1,850.00
Steering wheel clock spring	1	\$	480.00
RH driver knee airbag	1	\$	1,250.00
LH front air bag	1	\$	1,950.00
Dashboard	1	\$	2,200.00
Air bag ECU	1	\$	950.00
Air bag sensor x 2	2	\$	500.00
RH front seat belt	1	\$	550.00
LH front seat belt	1	\$	550.00
RH front seat belt buckle	1	\$	200.00
LH front seat belt buckle	1	\$	200.00
		\$	20,528.00
	Add 15%	\$	3,079.20
		\$	23,607.20

Front number plate	1	S. nett	\$	45.00
Engine coolant	1	S. nett	\$	30.00

To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality

\$ 120.00

To remove front damaged parts, to jack out front support panel, front body, and cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair bonnet hinge panel, front fender and inner panel, head lamp inner panel, front support panel, front chassis member, to replace damaged parts and adjust body panel alignment

\$ 900.00

To remove and install dashboard and centre console, including instrument panel, centre info screen, radio, climate control module. To remove & install RH/LH air bags, RH front knee iarbag, clockspring, and air bag ECU

\$ 400.00

To spray paint affected front and inner damaged portion inclusive of preparatory works and material

\$ 950.00

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality

\$ 50.00

To reprogram air bag ECU and clear fault codes.

\$ 380.00

\$ 26,482.20