

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts Er	n Automo	000,0	MR2200814
	STRIDES AUTOM	OTIVE SERVICES PTE LTD		Ref:	CS3/SMP22	008142/Cay2
	60 WOODLANDS E4SINGAPORE 75		Date:	21/00/2022	15/12/2022	
				Code:	SMR	
1.		CLAIN	И)			
	Insured Veh.	SHB 1699Y	Veh. Inspected	k	FBR 2342G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/08/22/2050	Excess (\$)		0.00	
	Assign From	HUAYEN ANA MAGNAYE	Assign Date		24/00/2022	15/12/2022
2.		Vehicle Partic	culars & Conditi	ion		
	Make & Model	_	c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
_	General					
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
1.	L/H Rear Tyre	Docarintie	on of Damages		mm	
+.	I	Description	on or Damages			
5.	General Information					
	Accident Date	17/08/2022	Inspection Dat	e	25/08/2022	
	Survey held at	BROTHER MOTORS	-			
	BLK 1016 YISHUN INDUSTRIAL PARK A #01-218 SINGAPORE 768758					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					