## PRESTIGE APPRAISER SERVICES

### VEHICLE INSPECTION REPORT

To: Mr Muhammad Hidhir Bin Mohamed Nastron

c/o Blk 1016 Yishun Industrial Park A

#01-218

Singapore 768758

Date

Our Ref Policy No

Sum Insured

Excess T/P Claim

Assigned By

: Mr Muhammad Hidhir Bin Mohamed Nastron

Assignment Date Accident Date

: 24th August 2022 : 17th August 2022 : 24th August 2022

Inspection Date Workshop Name

: Brother Motors

Survey Conducted At : Blk 1016 Yishun Industrial Park A

#01-218

Singapore 768758

## PARTICULARS OF VEHICLE

Registration No

: FBR 2342 G

Mileage

: 26904km

31st August 2022

PS/030/08/22

Make/Model Make/Model : Yamaha FZ
Type Of Body : Motorcycle

: Yamaha FZS

Engine No Chassis No

: HIDDEN : ME1RG44B8K0052959

Year Of Manu./Regn. : 2019/2020

Passenger Cap : 1 Passenger

Colour

: Blue

Others

: -

## CONDITION OF TYRES

Front Tyre Rear Tyre

: 5mm 110/70-17 Pirelli : 5mm 130/70-17 Pirelli

The above represent the estimated remaining life of the tyre treads.

## PRE-ACCIDENT CONDITION (Static tests only)

Handbrake Footbrake

: Serviceable : Serviceable

Body Work Paint Work

: Good : Good

Steering

: Serviceable

Others

2 .

#### POINT OF IMPACT

The vehicle sustained an impact on the front, L/H & R/H portion.

## GENERAL DESCRIPTION OF DAMAGES

The front fork, handle bar, exhaust muffler, main body frame were dented.

For details of damages please refer to schedule attached.

## **REMARKS:**

This survey was conducted strictly without prejudice.

# PRESTIGE APPRAISER SERVICES

Vehicle No: FBR 2342 G				Our Ref:		PS/030/08/22
Qty	Descriptions	Conditions		Repairer's Est.		Our Revised.
	LIST ITEMS	-111 <i>II</i> <b>h</b>	ф	580.00	\$	580.00 ✓
2	front fork	dented/bent	\$	102.00	Ψ	102.00 ✓
1	under bracket	dented				186.00 🗸
1	steering cone w/bearing	cracked		186.00		
1	front mudguard	sliced		185.00		185.00 🗸
1	front wheel rim	dented/warped		585.00		585.00 ✓
1	front wheel screw	bent		25.00		25.00 🗸
1	headlamp	serviceable		325.00		=
1	headlamp cowling	sliced		168.00		168.00✓
1	handle bar	dented/bent		195.00		195.00✓
		necessary		84.00		84.00 🗸
2	handle grip	sliced		76.00		76.00✓
2	handle balancer	sliced		85.00		85.00 ✓
1	L/H front signal lamp	sliced		85.00		85.00✓
1	brake lever			85.00		85.00 🗸
1	clutch lever	fractured		136.00		136.00 🗸
2	mirror	sliced		592.00		592.00 × NN
1	speedometer	dented/sliced				392.00 × 1414
1	fuel tank	dented - repair		689.00		132.00✓
1	L/H fuel tank side cover	sliced		132.00		
1 🖯	L/H fuel tank lower cover	sliced		95.00		95.00 🗸
1	R/H fuel tank side cover	sliced		132.00		132.00 ✓
1	R/H fuel tank lower cover	cracked		95.00		95.00 🗸
1	R/H front foot rest	sliced		72.00		72.00 ✓
1	R/H rear foot rest	sliced		72.00		72.00 <b>√</b>
	L/H front foot rest	sliced		72.00		72.00 🗸
1	L/H rear foot rest	sliced		72.00		<b>72.00</b> ✓
1		bent		82.00		82.00 🗸
1	gear pedal	dented/bent		580.00		580.00 × NN
1	exhaust muffler	sliced		95.00		95.00 🗸
1	exhaust muffler cover	serviceable		580.00		¥
1	rear wheel rim			320.00		320.00 🗸
1	cushion seat	cut		6,582.00		4,988.00
		3816		0,002.00		498.80
		-10% Less 10%		0.500.00	9	
		3434.40	,	6,582.00	,	4,409.20
	S/NETT ITEMS			00.00		22.00 🗸
1	front number plate	dented		28.00		
1	front tyre	wall cut		250.00		150.00 × NN
1	rear box	sliced		250.00		180.00 🗸
1	rear box bracket	dented/bent		200.00		160.00 🗸
1	IU unit	sliced 518		160.00		156.00 🗸
·	<u>Labour Charges &amp; Misc</u> To dismantle & replace damaged parts, panel beat where			650.00		520.00 350
	necessary.					
	To putty, apply primer & spray-paint or	n the affected portion.		400.00		300.00 🗸
	To align main body frame.	850		300.00		220.00 150
	Transportation charges.	4802.40		\$ 8,890.00	Ē	\$ 50.00 \$ 6,247.20
		L/S - 3841.92 = 3850 Page 2	?	3 day	'S	

# PRESTIGE APPRAISER SERVICES

Vehicle No: FBR 2342 G

Our Ref:

PS/030/08/22

Qty

Descriptions

**Conditions** 

Repairer's Est.

Our Revised.

Note: The repairer has agreed to undertake the repairs at our adjusted amount of \$5,000.00 lump sum corresponding to supply of parts, labour and spray-painting charges.

> Under normal circumstances, the estimated repair period would be **THREE (3)** days.

Pursuant to your instruction we have **not** authorised repairs

on your behalf.

PRESTIGE APPRAISER SERVICES

LOUIS S C NG CAE AMIMI (UK)

Licensed Appraiser

Dip. MTM. Automotive Engineer