



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22012570/Uny3m4 Date: 30/12/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMN 7094E	Veh. Inspected	SNA 2281X	
Policy No.	D22MTPV01012801	Coverage (\$)	0.00	
Claim No.	CMTD2204593/IJH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	15/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	GK82103552	Colour	MAROON	
Odometer	57664 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	DUNLOP	6 mm	
L/H Front Tyre	185/60 R15	DUNLOP	6 mm	
R/H Rear Tyre	185/60 R15	DUNLOP	6 mm	
L/H Rear Tyre	185/60 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/12/2022	Inspection Date	19/12/2022	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	